


Linear Interpolation and Dwell Cycle


Linear Interpolation

- Linear interpolation is used in part programming to make a straight cutting motion from the start position of the cut to the its end
- Always uses shortest distance the cutting tool path can take
- Motion is always straight line connecting the contour start and end points which is important in contouring and profiling machining
- Also angle cutting is performed by linear interpolation, which requires knowing the angular path the cutter has to take
- Three types of motion can be generated in linear interpolation
 - Horizontal motion-single axis only
 - Vertical motion-single axes only
 - Angular motion- multiple axes




Linear Interpolation: G01

- In G01 mode, the feedrate function (F) must be in effect to do the cutting
- Programming in either G00 or G01 has the same programmed end point but the difference is the feedrate and tool path
- An alarm will occur during the first run if no feedrate function is used. The feedrate specified for the first run will be always used unless changed during the program steps
- G01 is a modal, which means they can be omitted in all subsequent linear interpolation blocks. Only change of coordinate location is required (x,y, z)
- Linear motion is motion between two points. The start point is called the **departure**, the end point is called the **target**
- Departure point: defined by the current tool position
- Target point: defined by the target coordinates of the current block, which might be the starting point for another point




Single axis of motion

- The programmed tool motion along any single axis is always a motion parallel to that axis.
- all tool motion that are parallel to the table edge are single axis motion
- Most lathe operations (facing, shoulder turning, diameter turning) and all drilling operation are considered single axis motion operations
- A single axis motion can never me an angular motion. Workpiece is better fixed at the table axes to make most profiling and drilling operation single axes motion
- Another name is: orthogonal-horizontal or vertical only




Two axes Linear Interpolation

- A linear motion can also be programmed along two axes simultaneously.
- This is the case when departure and target have at least two coordinates different from each other
- The result of this two-axis motion is a straight line (G01) at an angle calculated by the controller
- The motion is still the shortest distance between the points



Three-axes of motion

- A simultaneous linear motion along three axes is possible on all CNC machines
- However, this kind of programming is not always easy specially with complex parts which requires extensive calculation for the tool path
- 3-axes are NOT done manually in most cases. A CAD/CAM software is commonly used (Pro/E)



Feedrate for linear operations


- The actual cutting feedrate for tool motion can be programmed in two modes
 - Per time (mm/min or inch/min)
 - Per spindle revolution (mm/rev or inch/rev)
- The selection depends on the machine type and dimensional units used. For milling and profiling operations we use feedrate per time., while for turning operations we use spindle revolution
- There is a range for feedrate for every CNC machine
- The feedrate values in table below represents the controller ranges depending on the technology in making the machine . It is unlikely to have such large feedrate close the maximum limits of the CNC machines

Minimum motion increment	MILLING
0.001 mm	0.0001 - 240000.00 mm/min
0.001 degree	0.0001 - 240000.00 deg/min
.0001 inch	.0001 - 240000.00 in/min

} Feedrate Ranges

Individual axes feedrate

- The machine controller translates the 2 or 3 axes feedrate into individual axes feedrate. This is not important during programming but it is good to explain how the controller behaves
- In order to keep the linear motion as the shortest motion between two points, the CNC unit must always calculate for each axis individually
- The computer will speed up on one axis and hold back the other axis, at the same time, depending on the angle of motion
- A straight line is actually a jagged line of small increments of x and y values that are very small to see



Example: Feedrate calculation

- Example:
 - G 70
 - G00 X 10.0 Y 6.0
 - G01 X 14.5 Y 7.25 F 12
- Find actual travel:
- $X_t = 14.5 - 10.0 = 4.5$ inch
- $Y_t = 7.25 - 6.0 = 1.25$
- $Z_t = 0$
- L is the compound motion calculated by Pythagorean theorem

$$L = \sqrt{X_t^2 + Y_t^2 + Z_t^2}$$

$$L = \sqrt{4.5^2 + 1.25^2 + 0^2} = 4.6703854$$

Feedrate calculation, continued

- Feed rates for x and y

$$F_x = \frac{X_t}{L \times F}$$

$$F_x = 4.5 / 4.6703854 \times 12 = 11.562215$$


$$F_y = \frac{Y_t}{L \times F}$$

$$F_y = 1.25 / 4.6703854 \times 12 = 3.2117263$$

$$F_z = \frac{Z_t}{L \times F}$$

$$F_x = 0 / 4.6703854 \times 12 = 0.0$$

Example: linear interpolation



➡ Example 1 :

(CLOCKWISE DIRECTION FROM P1)

```
G90 ...
G01 X1.0 Y3.0 F...
X3.0 Y4.0
X4.5
X6.5 Y3.0
X7.5
Y1.5
X4.5 Y0.5
X1.0 Y1.0
...
```

(ABSOLUTE MODE)

```
(P1 TO P2)
(P2 TO P3)
(P3 TO P4)
(P4 TO P5)
(P5 TO P6)
(P6 TO P7)
(P7 TO P8)
(P8 TO P1)
```

➡ Example 2 :

(COUNTERCLOCKWISE DIRECTION FROM P1)

```
G90 ...
G01 X4.5 Y0.5 F...
X7.5 Y1.5
Y3.0
X6.5
X4.5 Y4.0
X3.0
X1.0 Y3.0
Y1.0
...
```

(ABSOLUTE MODE)

```
(P1 TO P8)
(P8 TO P7)
(P7 TO P6)
(P6 TO P5)
(P5 TO P4)
(P4 TO P3)
(P3 TO P2)
(P2 TO P1)
```

Dwell time programming: G04-code

- Dwell is the *pause* in the program
- It is an intentional time delay applied during program processing
- In this time any motion is stopped while all other program commands and functions remain unaffected
- When the designated time expires, the control system resumes processing the program with the block immediately following the block command that contains the dwell
- Programming a dwell is very easy and useful in two main applications:
 - During actual cutting when the tool is in contact with the material
 - For operation of machine accessories, when no cutting takes place
- Each application is equally important to programmers but there NEVER used simultaneously

Application for cutting

- When cutting is removing material, it is in contact with the machined part.
- A dwell can be applied during machining for a number of reasons
 - Breaking chips while drilling, counter boring, grooving or parting off
 - Eliminate physical marks left on the part by end thrust of the cutting tool in case of turning, thrust is attributed to the tool pressure during cutting
 - Control deceleration of the cutting feed on a corner during fast feedrates.
- The Dwell command forces the machining operation to be fully completed in one block
- The programmer still has to supply the exact period of time required for the pause and must be sufficient, not too short and not too long

Applications for accessories

- Usually after certain miscellaneous functions (M-function)
- The dwell will allow completion of an accessory task during the dwell time, tailstock calibration, part catcher installation . Cleaning purposes are NOT allowed as well as any other manual operations using dwell time
- The machine spindle may either be stationary or rotating but it is NOT important if spindle is rotating or not because the tool is not in contact with the workpiece
- Dwell is also used when changing spindle speed usually after gear range change



Tailstock



Part
catchers

The G04 command

- Similar to G01, it has to be associated with a certain word address format, in this case the amount of time to dwell
- The correct addresses for dwell are X, P, or U (address U is only for lathe machines).
- The time selected is either in milliseconds or seconds
- Dwell command does not carry over to the following block unlike G01 or other command. It will perform the dwell ONLY for the same block (line of commands)
- Dwell is used in fixed cycles (drilling operations) without the G04 command. This is a special case for fixed cycle operations which will be covered in future lectures
- The structure for dwell function is:
 - X5.3 (for all machines except fixed cycles)
 - U5.3 (for lathe machines only)
 - P53 (all machines including fixed cycles)
- Remember 1 second = 1000 ms

Examples of dwell format

- G04 X 2.0 (preferred for long dwells)
- G04 P2000 (preferred for short or medium dwell, this address does NOT accept decimal points)
- G04 U 2.0 (lathe only-in seconds)
- in this example, the dwell is 2 seconds or 2000 milliseconds.
- G04 X0.5
- G04 P500
- G04 U0.5
- In this example, the dwell is 500 milliseconds
- In a CNC program, the dwell may appear in the following way, note how dwell is separate block and does not affect the following block:
- N21 G01 Z-1.5 F12.0
- N22 G04 X0.3
- N23 Z-2.7 F8.0
- Do NOT confuse the X address with the X-axis, there will be NO motion if the dwell command is used, CNC machine use the (T) letter for tool change only

Examples of dwell command

- The addresses X and U can also be programmed in milliseconds without decimal points
- G04 X2.0 is equal to G04 X2000
- Leading zero suppression is assumed in the format without decimal point (trailing zeros are required):
- X1 = X 0001 (1 millisecond)
- P10 = P0010 (10 milliseconds)
- P100 = P0100 (100 millisecond)
- If decimal point format is used, five digits before the decimal and three digits after decimal is the maximum allowed digits:
- Range of : 0.001 – 99999.999 seconds

Dwell time selection and minimum dwell time

- Dwell time is commonly in the order of few seconds (less than 10). And most often much less than a one second.
- Time delay for accessory operation is recommended by machine manufacturers to prevent machine damage
- Time delay during cutting is the machinist responsibility and requires attention NOT to over program dwell duration
- Make sure to calculate the minimum dwell that can do the job for higher productivity on the machine
- The minimum dwell is the time (in seconds) required to complete one revolution of the spindle:

$$\text{min. dwell} = \frac{60}{\text{rev/min}}$$

- Example: calculate the minimum dwell for spindle rotating of 420 rev/min:
- Divide the rev/min into 60 (60 seconds in one minute)
- $60/420 = 0.143$ seconds dwell
- G04 X0.143
- G04 P143
- G04 U 0.143
- It is a common practice to round up the minimum dwell time to avoid machine limits and ease of operations. For the preceding example, a typical roundup is:
- G04 X0.2

Time equivalent


- The dwell time for a required number of spindle revolutions is the time equivalent



$$Dwell_{\text{sec}} = \frac{60 \times n}{\text{rev}/\text{min}}$$





- n= required number of spindle revolution
- example: calculate the dwell time for full three spindle revolutions at spindle speed of 420 rev/min.
- Dwell = $60 \times 3 / 420 = 0.429$
- The program block representing the three spindle revolutions in terms of dwell time will be:
- G04 X0.429
- G04 P429
- G04 U0.429


Example

Tool	Operation	Tooling	Speed (rpm)	Feed (ipm)
1	Profile mill contour × 0.52 deep	0.5 <i>D</i> end mill	1200	8



Position	Diagram	Absolute coordinates	
		X	Y
②	 <p> $X = -.25 - .1 = -.35$ $Y = 4.00 + .25 = 4.25$ </p>	-0.35	4.25
③	 <p> $X = 2.00 + .25 = 2.25$ $Y = 4.25$ </p>	2.25	4.25

④	 <div data-bbox="989 454 1348 554" style="border: 1px solid black; padding: 5px; width: fit-content;"> $X = 2.25$ $Y = 1.00 + .25 = 1.25$ </div>	2.25	1.25
⑤	 <div data-bbox="989 699 1348 799" style="border: 1px solid black; padding: 5px; width: fit-content;"> $X = 5.00 + .25 = 5.25$ $Y = 1.25$ </div>	5.25	1.25
⑥	 <div data-bbox="1178 949 1348 1049" style="border: 1px solid black; padding: 5px; width: fit-content;"> $X = 5.25$ $Y = -.25$ </div>	5.25	-.25
⑦	 <div data-bbox="1178 1199 1348 1299" style="border: 1px solid black; padding: 5px; width: fit-content;"> $X = -.25$ $Y = -.25$ </div>	-.25	-.25


<p>⑧</p>	 <p style="text-align: right;"> $X = .25$ $Y = 4.00 + .25 = 4.25$ </p>	<p>-.25</p>	<p>4.25</p>
----------	--	-------------	-------------

Introduction to Hole operations


CAD/CAM

Drill center, or ream cycle

- A G81 cause the machine to rapid the tool from an initial position to a specified “plane” before drilling
- Then drill to a defined depth at a given feedrate
- Then move out of the drilled hole to the original starting “plane”
- Then rapid motion to the center of the new next hole defined by coordinates (X,Y)
- Any drilling operation can be either in absolute or incremental dimensions specified before drilling
- Command :
- G81 X_n Y_n Z_n R_n F_n
- X_n Y_n : numeric vlaue (n) specify the location of hole drilling
- Z_n : numeric value (n) specify the depth of the drill
- R_n :
 - Absolute: specifies the distance to R-plane from Z₀
 - Incremental: specifies the distance below the Z-initial to R_n



Drill center or ream example



Absolute Coordinates


```
N0060 G90
N0070 G81 X2. Y3. Z-.25 R.1 F7
```

Incremental Coordinates


```
N0060 G91
N0070 G81 X.75 Y.5 Z-.35 R-.1 F
```

Counter bore or spot face cycle

- Word address command: G82
- G82 cycle causes the machine to rapid the tool from Z-initial to R-plane, then bore the hole to a depth of Z_n at feed rate of F_n , then dwell for P_n seconds at depth Z_n , then rapid back to R-plane and finally rapid movement to the next hole if a new X, Y are given in the next block
- Complete command block:
 - G82 X_n Y_n Z_n R_n P_n F_n



Counter bore or spot face example



Absolute Coordinates

N004 G90

N005 G82 X2.0 Y4.0 Z-0.125 R0.1 P500 F6

Incremental Coordinates

N004 G91

N005 G82 X0.1 Y0.75 Z-0.225 R-1.0 P500 F6