




# Properties of Engineering Materials Phase Diagrams

Dr. Eng. Yazan Al-Zain

Department of Industrial Engineering

University of Jordan

# Introduction



Phase diagram for pure H<sub>2</sub>O

# Definitions & Basic Concepts


- **Components:** are pure metals and/or compounds of which an alloy is composed.
  - E.g.; in a copper–zinc brass, the components are Cu and Zn.
- **System:** the series of possible alloys consisting of the same components, but without regard to alloy composition (e.g., the iron–carbon system).

# Solubility Limit

- ***Solubility Limit***: maximum concentration of solute atoms that may dissolve in the solvent to form a solid solution.
  - The addition of solute in excess of this solubility limit results in the formation of another solid solution or compound that has a distinctly different composition.

# Solubility Limit

For example, at 20° C the maximum solubility of sugar in water is 65 wt%.



**Figure 9.1** The solubility of sugar ( $C_{12}H_{22}O_{11}$ ) in a sugar–water syrup.

# Phases

- **A Phase:** a homogeneous portion of a system that has uniform physical and chemical characteristics.
  - Every pure material is considered to be a phase; so also is every solid, liquid, and gaseous solution.
  - For example, the sugar–water syrup solution just discussed is one phase, and solid sugar is another.
- In phase diagrams, different phases are separated by boundaries; these boundaries are called Phase Boundaries.

# Microstructure

- Many times, the physical properties and, in particular, the mechanical behavior of a material depend on the microstructure.
  - characterized by the *number of phases present, their proportions, and the manner in which they are distributed or arranged.*
  - depends on such variables as *the alloying elements present, their concentrations, and the heat treatment of the alloy.*

# Phase Equilibria

- ***Equilibrium*** is described in terms of the ***free energy***.
  - free energy is a function of the *internal energy of a system*, and also the *randomness or disorder* of the atoms or molecules (or entropy).
- A system is at equilibrium if its free energy is at a minimum under some specified combination of temperature, pressure, and composition.
  - In a macroscopic sense, this means that the characteristics of the system do not change with time but persist indefinitely; that is, the system is stable.



# Phase Equilibria


- ***Phase Equilibrium***: equilibrium as it applies to systems in which more than one phase may exist.
  - A change in temperature, pressure, and/or composition for a system in equilibrium will result in an increase in the free energy and in a possible spontaneous change to another state whereby the free energy is lowered.
- Sugar has 65% solubility in water at 20° C, but would increase up to 80% when temperature rises to 100° C.

# Phase Equilibria

- In many metallurgical and materials systems of interest, phase equilibrium involves just solid phases.
- ***Metastable*** state: when a state of equilibrium is never completely achieved as the rate of approach to equilibrium is extremely slow.

# One-Component (Unary) Phase Diagrams

- Three externally controllable parameters that will affect phase structure: temperature, pressure, and composition
  - Phase diagrams are constructed when various combinations of these parameters are plotted against one another.
- One component system: composition is held constant.



**Figure 9.2** Pressure–temperature phase diagram for H<sub>2</sub>O. Intersection of the dashed horizontal line at 1 atm pressure with the solid–liquid phase boundary (point 2) corresponds to the melting point at this pressure ( $T = 0^{\circ}\text{C}$ ). Similarly, point 3, the intersection with the liquid–vapor boundary, represents the boiling point ( $T = 100^{\circ}\text{C}$ ).


# Binary Phase Diagrams ( $P = 101.3 \text{ kPa}$ )

## Binary Isomorphous Systems

The liquid  $L$  is a homogeneous liquid solution composed of both Cu and Ni.

The  $\alpha$  phase is a substitutional solid solution consisting of both Cu and Ni atoms, and having an FCC crystal structure.

Below  $1085^\circ \text{C}$ , both Ni & Cu are totally soluble in each other for all compositions. Hence, Cu-Ni system is termed *isomorphous*.



**Figure 9.3 (a)** The Cu–Ni phase diagram.

# Interpretation of Phase Diagrams

## Phases Present


Locate the temperature–composition point on the diagram and notes the phase(s) with which the corresponding phase field is labeled.

Example 1.

Point A:

Example 2.


Point:



# Interpretation of Phase Diagrams

## Determination of Phase Compositions

- (1) A tie line is constructed across the two-phase region at the temperature of the alloy.
- (2) The intersections of the tie line and the phase boundaries on either side are noted.
- (3) Perpendiculars are dropped from these intersections to the horizontal composition axis, from which the composition of each of the respective phases is read.




**Figure 9.3 (b)** A portion of the Cu– Ni phase diagram for which compositions and phase amounts are determined at point *B*.

# Interpretation of Phase Diagrams

## Determination of Phase Compositions

The perpendicular from the intersection of the tie line with the liquidus boundary meets the composition axis at 31.5 wt% Ni–68.5 wt% Cu, which is the composition of the liquid phase,  $C_L$ .

Likewise, for the solidus–tie line intersection, we find a composition for the  $\alpha$  solid solution phase,  $C_\alpha$ , of 42.5 wt% Ni–57.5 wt% Cu.




**Figure 9.3 (b)** A portion of the Cu– Ni phase diagram for which compositions and phase amounts are determined at point  $B$ .

# Interpretation of Phase Diagrams

## Determination of Phase Amounts / Inverse Lever Rule

- (1) The tie line is constructed across the two-phase region at the temperature of the alloy.
- (2) The overall alloy composition is located on the tie line.
- (3) The fraction of one phase is computed by taking the length of tie line from the overall alloy composition to the phase boundary for the *other* phase, and dividing by the total tie line length.
- (4) The fraction of the other phase is determined in the same manner.



**Figure 9.3 (b)** A portion of the Cu– Ni phase diagram for which compositions and phase amounts are determined at point *B*.



# Interpretation of Phase Diagrams

## Determination of Phase Amounts / Inverse Lever Rule

Example: Let's calculate the amounts of the liquid and  $\alpha$  phases at point  $B$ .


(1) The overall composition at  $B$  is  $C_0 = 35$  wt.% Ni.

(2) Fraction of liquid =

$$W_L = \frac{S}{R + S}$$

$$W_L = \frac{C_\alpha - C_0}{C_\alpha - C_L}$$

$$W_L = \frac{42.5 - 35}{42.5 - 31.5} = 0.68$$



**Figure 9.3 (b)** A portion of the Cu–Ni phase diagram for which compositions and phase amounts are determined at point  $B$ .

# Development of Microstructure in Isomorphous Alloys / Equilibrium Cooling

At 1300° C, point *a*, the alloy is completely liquid (of composition 35 wt% Ni–65 wt% Cu)


At point *b*,  $\alpha$  begins to form. composition: 46 wt% Ni. *L* composition: 35 wt% Ni.

The fraction of the  $\alpha$  phase will increase with continued cooling.

At 1250° C, point *c*.  $\alpha$  = 43 wt% Ni, *L* = 32 wt%Ni.

At 1220° C, point *d*.  $\alpha$  = 35 wt% Ni, *L* = 24 wt%Ni.

below 1220° C, point *e*.  $\alpha$  = 35 wt% Ni, and no *L*.



# Development of Microstructure in Isomorphous Alloys / Nonequilibrium Cooling

- Equilibrium cooling: a result of diffusion.
  - Readjustments in the compositions of the liquid and solid phases in accordance with the phase diagram
- Nonequilibrium cooling: cooling rate is rapid, no time for diffusion.
  - No time for (ideal) readjustments of phases.

# Development of Microstructure in Isomorphous Alloys / Nonequilibrium Cooling


Nonequilibrium cooling:

- Shift of the solidus line to lower temperatures.

- An average composition results rather than a fixed one.

- Segregation results: concentration gradients are established across the grains.

- the center of each grain, which is the first part to freeze, is rich in the high melting element (Ni), whereas the concentration of the low-melting element increases with position from this region to the grain boundary (termed **core structure**).




# Development of Microstructure in Isomorphous Alloys / Nonequilibrium Cooling

- Equilibrium cooling: a result of diffusion.
  - Readjustments in the compositions of the liquid and solid phases in accordance with the phase diagram
- Nonequilibrium cooling: cooling rate is rapid, no time for diffusion.
  - No time for (ideal) readjustments of phases.

# Mechanical Properties of Isomorphous Alloys

- For all temperatures and compositions below the melting temperature of the lowest-melting component, only a single solid phase will exist.
  - Therefore, each component will experience solid-solution strengthening, or an increase in strength and hardness by additions of the other component.

# Mechanical Properties of Isomorphous Alloys



**Figure 9.6** For the copper–nickel system, (a) tensile strength versus composition, and (b) ductility (%EL) versus composition at room temperature. A solid solution exists over all compositions for this system.

# Binary Eutectic Systems

Eutectic:  
transformation of  
**liquid** into **two solids**.

Limited solubility of  
one element into the  
other.

Solvus line: the solid  
solubility limit line  
separating the  $\alpha$  and  
 $\alpha+\beta$  phase regions

Maximum solubility of  
Ag in Cu = 8 wt% Ag  
at 779 ° C.






Figure 9.7 The copper–silver phase diagram.



# Binary Eutectic Systems

**Invariant point** = eutectic point: point at which the two liquidus lines meet.




The eutectic reaction, upon cooling, is similar to solidification for pure components in that the reaction proceeds to completion at a constant temperature.

# Development of Microstructure in Eutectic alloys

- At  $a$  (350 °C): liquid with  $C_1$  composition.
- At  $b$  (330 °C):  $\alpha$  starts to form within the  $L$ .
- At  $c$  (275 °C): single  $\alpha$  phase, no further transformation upon cooling.

Applicable for alloys containing between 0 and about 2 wt% Sn.




**Figure 9.11** Schematic representations of the equilibrium microstructures for a lead-tin alloy of composition  $C_1$  as it is cooled from the liquid-phase region.

# Development of Microstructure in Eutectic alloys


- At  $d$ : liquid with  $C_2$  composition.
- At  $e$ :  $\alpha$  forms and  $L$  is present.
- At  $f$ : single  $\alpha$  phase, no more  $L$ .
- At  $g$ : solubility limit of Sn in Pb is exceeded,  $\beta$  precipitates form.
- Crossing  $g$ :  $\beta$  particles will grow in size because the mass fraction of the phase increases slightly with decreasing temperature.

Applicable for alloys containing about 2 wt% Sn to 18.3 wt% Sn



**Figure 9.11** Schematic representations of the equilibrium microstructures for a lead–tin alloy of composition  $C_2$  as it is cooled from the liquid-phase region.


# Development of Microstructure in Eutectic alloys



**Figure 9.13** Schematic representations of the equilibrium microstructures for a lead–tin alloy of eutectic composition  $C_3$  above and below the eutectic temperature.

# Development of Microstructure in Eutectic alloys

- At  $h$  : liquid with  $C_3$  composition.
- At  $i$  (crossing the eutectic temperature line):  $L$  transforms to  $\alpha$  and  $\beta$ .



- The microstructure (eutectic structure) of the solid that results from this transformation consists of alternating layers (sometimes called lamellae) of the  $\alpha$  and  $\beta$  phases that form simultaneously during the transformation.
- No pronounced microstructural changes upon cooling below point  $i$ .

Applicable for the alloy containing 61.9 wt% Sn only.


# Development of Microstructure in Eutectic alloys



**Figure 9.14**  
Photomicrograph showing the microstructure of a lead–tin alloy of eutectic composition. This microstructure consists of alternating layers of a lead-rich  $\alpha$ -phase solid solution (dark layers), and a tin-rich  $\beta$ -phase solid solution (light layers). 375  $\times$ .


# Development of Microstructure in Eutectic alloys

- Lead atoms diffuse toward the  $\alpha$ -phase layers because this  $\alpha$  phase is lead-rich (18.3 wt% Sn–81.7 wt% Pb); conversely, the direction of diffusion of tin is in the direction of the  $\beta$ , tin-rich (97.8 wt% Sn–2.2 wt% Pb) layers.
- The eutectic structure forms in these alternating layers because, for this lamellar configuration, atomic diffusion of lead and tin need only occur over relatively short distances.



**Figure 9.15** Schematic representation of the formation of the eutectic structure for the lead–tin system. Directions of diffusion of tin and lead atoms are indicated by blue and red arrows, respectively.

# Development of Microstructure in Eutectic alloys




**Figure 9.16**  
 Schematic representations of the equilibrium microstructures for a lead-tin alloy of composition  $C_4$  as it is cooled from the liquid-phase region.



# Development of Microstructure in Eutectic alloys

- At  $j$ : liquid with  $C_4$  composition.
- At  $k$ :  $\alpha$  starts to form.
- At  $l$ : more  $\alpha$  forms where it grows in size.
  - $\alpha$  that forms at temperatures higher than the eutectic temperature is called proeutectoid or **primary**  $\alpha$ .
- At  $m$ : eutectic temperature is crossed. Here, the remaining liquid which had the eutectic composition at point I will experience a eutectic reaction; alternating layers of  $\alpha$  (**eutectic**  $\alpha$ ) and  $\beta$  phases.

# Development of Microstructure in Eutectic alloys



**Figure 9.17** Photomicrograph showing the microstructure of a lead–tin alloy of composition 50 wt% Sn–50 wt% Pb. This microstructure is composed of a primary lead-rich  $\alpha$  phase (large dark regions) within a lamellar eutectic structure consisting of a tin-rich  $\beta$  phase (light layers) and a lead-rich  $\alpha$  phase (dark layers). 400  $\times$ .


# Development of Microstructure in Eutectic alloys

$$W_e = W_L = \frac{P}{P + Q} \quad \text{Weight fraction of the eutectic microconstituent}$$

$$W_{\alpha'} = \frac{Q}{P + Q} \quad \text{Weight fraction of the primary } \alpha.$$

$$W_{\alpha} = \frac{Q + R}{P + Q + R} \quad \text{Weight fraction of total } \alpha.$$


$$W_{\beta} = \frac{P}{P + Q + R} \quad \text{Weight fraction of } \beta.$$





**Figure 9.18** The lead–tin phase diagram used in computations for relative amounts of primary  $\alpha$  and eutectic microconstituents for an alloy of composition  $C'_4$ .

# Eutectoid and Peritectic Reactions

- At  $E$  (eutectoid point): eutectoid reaction takes place on cooling; one solid transforms into 2 other solids.




- At  $P$  (peritectic point): peritectic reaction takes place on cooling; a solid and a liquid transform into another solid.



**Figure 9.21** A region of the copper–zinc phase diagram that has been enlarged to show eutectoid and peritectic invariant points, labeled  $E$  (560 °C, 74 wt% Zn) and  $P$  (598 °C, 78.6 wt% Zn), respectively.

# Congruent and Incongruent Transformations

- **Congruent transformation:** no compositional alterations upon transformation.
  - E.g.; solidification of pure metals, allotropic transformations, etc.
  - Incongruent: Eutectoid and eutectic reactions, melting of an alloy, etc.



**Figure 9.22** A portion of the Ni–Ti phase diagram on which is shown a congruent melting point for the  $\gamma$ -phase solid solution at 1310 °C and 44.9 wt% Ti.

# The Gibbs Phase Rule

- ***Gibbs Phase Rule***: a rule that represents a criterion for the number of phases that will coexist within a system at equilibrium; expressed by:

$$P + F = C + N$$

*P*: the number of phases present.



*F*: *number of degrees of freedom* or the number of externally controlled variables (e.g., temperature, pressure, composition) which must be specified to completely define the state of the system.

Alternatively, *F* is the number of these variables that can be changed independently without altering the number of phases that coexist at equilibrium.



*C*: the number of components in the system.

*N*: the number of noncompositional variables (e.g., temperature and pressure).

# The Gibbs Phase Rule



- **Gibbs Phase Rule:** applying to the copper–silver system, Fig. 9.7.
  - 1. Pressure is constant = 1 atm, so  $N = 1$  (1—temperature is the only noncompositional variable).
  - 2.  $C = 2$ , since we have Cu and Ag.
  - Hence:  $P + F = 3$    $F = 3 - P$
  - Considering single-phase fields,  $P = 1$ .   $F = 2$
  - This means that to completely describe the characteristics of any alloy that exists within one of these phase fields, we must specify two parameters; these are composition and temperature.

# The Gibbs Phase Rule


- **Gibbs Phase Rule:** applying to the copper–silver system, Fig. 9.7.
  - 1. Pressure is constant = 1 atm, so  $N = 1$  (1—temperature is the only noncompositional variable).
  - 2.  $C = 2$ , since we have Cu and Ag.
  - Hence:  $P + F = 3$    $F = 3 - P$
  - Considering two-phase fields,  $P = 2$ .   $F = 1$
  - Thus, it is necessary to specify either temperature or the composition of one of the phases to completely define the system.



# The Gibbs Phase Rule

- **Gibbs Phase Rule:** applying to the copper–silver system, Fig. 9.7.
  - 1. Pressure is constant = 1 atm, so  $N = 1$  (1—temperature is the only noncompositional variable).
  - 2.  $C = 2$ , since we have Cu and Ag.
  - Hence:  $P + F = 3$    $F = 3 - P$
  - Considering three phases,  $P = 3$ .   $F = 0$
  - This means that the compositions of all three phases as well as the temperature are fixed (eutectic point).

# The Iron – Carbon (Carbide: Fe<sub>3</sub>C) System



**Figure 9.24** The iron-iron carbide phase diagram.

# The Iron – Carbon (Carbide: $\text{Fe}_3\text{C}$ ) System

## ■ $\alpha$ -Fe (ferrite) - solid solution of C in BCC Fe

- Stable up to  $\sim 910$  °C.
- The maximum solubility of C in  $\alpha$ -Fe is  $\sim 0.022$  wt%
- Transforms to FCC  $\gamma$ -Fe at  $\sim 910$  °C.
- When subjected to quenching, C can remain in the  $\alpha$  solid solution, but soon precipitation of phases commences, by an aging treatment.
- Ferrite is plastic, and in the annealed state it has large elongation ( $\sim 40\%$ ).
- Ferrite is soft (Brinell hardness is 65-130).
- Ferrite is strongly magnetic up to  $770$  °C.

## ■ $\gamma$ -Fe (austenite) - solid solution of C in FCC Fe

- The maximum solubility of C in  $\gamma$ -Fe is  $\sim 2.14$  wt %.
- Transforms to BCC  $\delta$ -Fe at  $\sim 1400$  °C.
- Austenite is soft but harder than ferrite, ductile and its elongation is similar to ferrite.
- Lower conductivity of heat and electricity as compared to ferrite and is paramagnetic.

# The Iron – Carbon (Carbide: Fe<sub>3</sub>C) System

- **δ -Fe (ferrite) - solid solution of C in BCC Fe**
  - Same crystal structure as α-Fe and is also called ferrite.
  - Stable only above ~1400 °C
  - Solubility of C in δ -Fe is 5 times higher than in α-Fe.
- **Fe<sub>3</sub>C (iron carbide or cementite)**
  - Cementite is an intermetallic compound and is almost always present in a metastable state.
  - Cementite is present even in relatively slowly cooled alloys; a long holding at elevated temperatures is required to decompose cementite to α-iron and graphite.
  - Cementite is brittle and exhibits great hardness (Brinell hardness ~800).
  - It is weakly magnetic up to 210 °C, poor conductor of heat and electricity and has a complicated rhombic lattice.
- Liquid solution forms at ~1538 °C in pure iron; this temperature decreases on alloying with C and increases as C content reaches 4.3 wt.%.

# The Iron – Carbon (Carbide: Fe<sub>3</sub>C) System


- The eutectoid reaction is the transformation of one solid into two other solids. In the case of Fe-C system it represents the decomposition of the austenite into ferrite and cementite on cooling.
- The eutectoid reaction takes place at 727 °C and 0.76 wt. %C




- The eutectic reaction on the other hand, is the transformation of one liquid into two solids. In the case of Fe-C system it represents the transformation of the liquid into austenite and cementite on cooling.
- The eutectic reaction takes place at 1147 °C and 4.3 wt. %C.



# The Iron – Carbon (Carbide: Fe<sub>3</sub>C) System



# The Iron – Carbon (Carbide: $\text{Fe}_3\text{C}$ ) System



The transformation from austenite to ferrite is hampered due to presence of C in austenite.

FCC: more space for C atoms. Higher solubility.

During transformation from  $\gamma$  to  $\alpha$ , almost all C precipitates as  $\text{Fe}_3\text{C}$  from the austenite.

[1]  $\gamma \rightarrow \alpha$

[2] Precipitation of C in the form of  $\text{Fe}_3\text{C}$ .

[3] Coagulation of the carbides.

The first two processes occur almost simultaneously, with the formation of a lamellar mixture of ferrite and cementite.

In  $\gamma$ : C is distributed randomly, thus  $\text{Fe}_3\text{C}$  and ferrite nucleate at C-rich and -depleted regions, respectively.


# The Iron – Carbon (Carbide: $\text{Fe}_3\text{C}$ ) System



Pearlite: is a layered structure of ferrite and cementite. It forms if steel in the austenite region were allowed to cool slowly. (Simultaneous mixture of  $\alpha$  and  $\text{Fe}_3\text{C}$ )


An annealed structure, hence soft (low physical properties).

Pearlite nuclei appear on defects such as grain boundaries. Its diffusion rate increases as cooling temp. is decreased (plate-to-plate distance decreases and fineness increases).






# The Iron – Carbon (Carbide: Fe<sub>3</sub>C) System




In hypoeutectoid steel, proeutectoid ferrite forms at *d*; the rest of austenite transforms into eutectoid ferrite and cementite.

Hypoeutectoid reaction takes place when:  
 $0.022 < C \text{ wt.\%} < 0.76$




# The Iron – Carbon (Carbide: $\text{Fe}_3\text{C}$ ) System

In this micrograph, proeutectoid  $\alpha$  is the large white grains while eutectoid  $\alpha$  is the white regions between the black plates (cementite).




# The Iron – Carbon (Carbide: Fe<sub>3</sub>C) System



In hypereutectoid steel, proeutectoid cementite forms at  $h$ ; the rest of austenite transforms into eutectoid ferrite and cementite.

Hypereutectoid reaction takes place when:  
 $0.76 < \text{C wt.\%} < 2.14$



# The Iron – Carbon (Carbide: $\text{Fe}_3\text{C}$ ) System

In this micrograph, proeutectoid cementite is the large white areas while black and white plates represent eutectoid cementite and eutectoid  $\alpha$ .

