

For Proctor's Remarks

Q1: Why is the depth of cut usually much larger in rough machining compared to finishing? (3 Marks)

depth of cut is larger than in rough machining > finishing

because of the ~~forces~~ plastic deformation & shear strains $\uparrow\uparrow$ is much higher than finishing process
& because of the compressive force that will

because also of the high cutting forces & power & speeds

compress the material due to $\rightarrow$ depth of cut in rough machining be larger than in finishing

& rough machining conduct so much heat. ~~that~~ ~~that~~

Q2: Explain the effect of temperature rise during machining. (3 Marks) (3 Marks)

- produce hot chips
- reduce the tool life
- ~~reduce~~ ~~the~~ surface finish & integrity
poor $\rightarrow$
- ~~wear~~ ~~also~~ uneven dimension
- ~~wear~~ crater wear

Q3: Describe how excellence in metal-cutting practices can impact the national economy. (3 Marks) (ABET SOH)

- 1- increase the work force & reduce unemployment
- 2- Increase productivity, technology & innovation
- 3- environment sustainability & reduce waste & encourage recycling
- 4- increase gross product.



Q4: What are the basic components of traditional machine tools, and what are their main functions? (4Marks)

1- Bed/structure/frame

It's hold the cutting tool, material workpiece & other various moving parts in the machine, It should be minimum deflection & high moment of inertia.

2- power unit → electrical motor

3- transmission system → transmit the power from the power unit to ~~other~~ moving parts. like spindle

4- spindle → It may hold the material workpiece → like turning or hold the cutting tool → like drilling & milling

5- Work table → If the spindle hold the work piece material It will hold the cutting tool & vice versa

6- tail stock → hold the workpiece

7- head stock → left end of the machine to hold various moving parts like ~~like spindle~~ & power unit.

Q5) Rate the following materials according to their machinability index (2.5)

↑ not easy to machine It's abrasive
Martensitic stainless steel, ferritic stainless steel, Polymer matrix composite, Aluminum, Magnesium
↓
very easy & good dimensional accuracy
easy and good machinability
very hard & not easy to work with not good machinability
very easy & very good

Q6) Briefly illustrate the difference between the manufacturing process of carbide and ceramic inserts (2.5)

Carbide is consist of tungsten, titanium & tantalum mixed together as fine powders & add to them cobalt then ~~then~~ into high temperature to do (sintering) then the cobalt will be good for abrasive cutting edge.

Ceramics → also we do sintering process for Alumina & boron nitride they ~~use~~ as inserts & they are portable (we can change them) & always the ceramics inserts is much hard & effective than carbides inserts. because of that hardness is larger ---



Q7) Tool life tests on lathe provided the following data: 1) at cutting speed 800 ft/min the tool life was 52.5 minute, 2) at cutting speed 600 ft/min the tool life was 185 min. What is the expected tool life at a cutting speed of 900 ft/min. (5 Marks)

$$1- \begin{matrix} V_1 = 800 \text{ ft/min} \\ T_1 = 52.5 \text{ min} \end{matrix}$$

$$2- \begin{matrix} V_2 = 600 \text{ ft/min} \\ T_2 = 185 \text{ min} \end{matrix}$$

$$V_1 T_1^n = V_2 T_2^n$$

$$\frac{(800)(52.5)^n}{800} = \frac{600(185)^n}{800}$$

$$\frac{52.5^n}{185^n} = \frac{600}{800}$$

$$\left(\frac{52.5}{185}\right)^n = \frac{600}{800}$$

$$n = 0.228 \approx 0.23$$

$$800 (52.5)^{0.23} = T_3 (900)^{0.23} \rightarrow T_3 = 416.15 \text{ min}$$

Q8) An orthogonal turning process performed on a material that has 130 MPa shear strength with 10° rake angle tool, 4mm width of the cut, 1 mm depth of the cut, the chip thickness was 1.2 mm and the coefficient of friction on the rake face was 1.7. Calculate
a) the required cutting forces, b) the percentage of power dissipated in friction if the cutting velocity is 120 m/min. (10 Marks)

$$\tau_s = 130 \text{ MPa}$$

$$\alpha = 10^\circ$$

$$W = 4 \text{ mm}$$

$$t_1 = t_o = 1 \text{ mm}$$

$$t_2 = t_c = 1.2 \text{ mm}$$

$$\mu = 1.7$$

$$\tau_s = 130 = \frac{F_s}{W t_o} \sin \phi$$



a) required cutting forces F_t, F_c

$$\tau_s = \frac{F_s}{w \cdot t_o} \sin \phi$$

$$\phi = \tan^{-1} \left(\frac{r \cos \alpha}{1 - r \sin \alpha} \right) = \tan^{-1} \left(\frac{0.83 \cos(10)}{1 - 0.83 \sin(10)} \right) = 43.68^\circ$$

$$r = \frac{t_o}{t_c} = \frac{1}{1.2} = 0.83$$

$$F_s = ?$$

$$130 = \frac{F_s}{4 \times 1} \sin(43.68) \rightarrow F_s = 752.9 \text{ N}$$

$$\beta = \tan^{-1}(\mu) = \tan^{-1}(1.7) = 59.53^\circ$$

$$752.9 = R \cos(43.68 + 59.53 - 10) \rightarrow R = -13445.66 \text{ N}$$

$$= 13445.66 \text{ N}$$

$$F_c = R \cos(\beta - \alpha) = -8726.9 \text{ N} = 8726.9 \text{ N}$$

$$F_t = R \sin(\beta - \alpha) = -10228.73 \text{ N} = 10228.73 \text{ N}$$

$$R = \sqrt{F_t^2 + F_c^2} \rightarrow \text{so I put them +ve}$$

b) power dissipated in friction

$$V_{\text{cutting}} = 120 \text{ m/min}$$

$$P = F V_c$$

$$P_{\text{Tot.}} = F_c V$$

$$= 1047228$$

$$\frac{V}{\sin(90 - \phi + \alpha)} = \frac{V_c}{\sin \phi}$$

$$\frac{120}{\sin(90 - 43.68 + 10)} = \frac{V_c}{\sin(43.68)} \rightarrow V_c = 99.59 \text{ m/min}$$

$$F = R \sin \beta$$

$$= 13445.66 \sin(59.53) = 11588.74 \text{ N}$$

$$P = 11588.74 \times 99.59$$

$$P = 1154123 \text{ N/mm}$$

$$\frac{1154123}{1047228} = 1.1\%$$

$$\frac{F V_c}{F_c V} = \frac{F_r}{F_c} = 1.1\%$$