


Metal cutting: is family of shaping operation, the common factor between them is the removal of material from a starting workpart so the remaining become the desired geometry.

Metal cutting is process consists in removing a material (layer) of metal from blank to obtain the desired required shape & dimensions & with the specified quality of surface finish




### • Machining

↳ It's performed AFTER other manufacturing process such as forging, cutting, bar drawing

↓  
these processes create the general shape of the workpiece (starting workpart)

↳ Machining provides the final shape (desired dimensions & shape) & special geometric details that other process can't create.

## Factor Influencing the chip removal (Formation) process



### Basic Machine Variables

✂ cutting speed → the rate at which the workpiece passes by cutting edge (m/s, mm/s)

↓

we can define it

the speed at which the <sup>(chip)</sup> material is removed from the surfaces of the workpiece.

rotational speed →  $V = \pi D N$

↓  
cutting speed

↓  
Dia.

↓  
rotational speed  
(rpm)


revolution per minute.

✂ cutting feed → the rate at which the cutting tool advances into work piece (mm/rev), (mm/min)

✂ Depth of the cut → the distance the tool is set into the work



Machining technology أساسيات



الاجزاء التي يتكون منها (كل ماكينة)  
cutting tool material

holders التي يثبتون بها workpiece

الاجزاء المختلفة التي يتكون منها الحركة النسبية ما بين الـ workpiece و cutting tool  
material

support various parts like workpiece, cutting tool & moving parts & provide sufficient

1 - Frame / structure / Bed

support various part &

strength, rigidity & support to the machine

الاجزاء التي يتكون منها الـ machine

وذلك لتحمّل الـ load التي تجلبها الأجزاء المختلفة و الـ load التي تجلبها الأجزاء المختلفة

work piece material

minimum deflections

ما كان الـ material removed by cutting action process

support

بعضها حركة نسبية ما بين الـ work piece material و cutting tool material

و الـ material المتحركة في الـ structure / frame / Bed

structure (Bed)

deflection بالارتداد في الـ structure (Bed) فأمره النسبية حتمًا أن يحد من الـ quality في الأسفل

(modulus of elasticity) و كذا الـ modulus و كذا الـ deflection

(mass moment of inertia) second moment of area

لازم يكون على حدّ ما أن يكون الـ minimum deflection

easier control / high efficiency electrical (motor)

power unit

transmit the motion from the power unit to the moving part

الاجراء التي يجرها الـ machine tool

power unit

transmission system

pull pulley or gears & nuts box

live back



Spindle - 2

(turning process) work piece material و (drilling process) cutting tool material

و الـ spindle يثبتها في مكانها و يجعلها تدور حول المركز و يضمن ان يكون الدوران حول المركز

# Mechanism of metal cutting process

Work table - 0


workpiece material ← Spindel

cutting tool ← table

(القطع)

القطع، لينة بين spindle و table  
cutting tool

to hold & rotate the work piece



permanently fixed at the left end of the lathe, inside it the drive mechanism for rotating the work piece is situated

the drive mechanism is a gear box which gives the required speed & direction of rotation to the work

Lead screw of

It also support

transmits power

a hollow shaft called spindle

from the head stock

to the carriage for screw thread cutting operation

carriage → It moves the

tool allows

the guide base parallel

to the axis of rotation

It contains parts that

holds the tool & control the motion of the tool

of the tool

gear box drives the spindle which rotates on its axis


tail stock →

It's support the right end of the work piece & also useful

supporting the tool like

a drill bit during the

drilling operation on the lathe



this motion gives the depth of cut in turning  
provide the motion in the direction perpendicular to the axis of rotation

Machine tool is the device that contain the workpiece holders,

cutting tool & other parts that control the relative motion between the work piece material & the cutting tool material

### 1- Bed / structure / frame

- It's the frame of the machine, it support various parts like work piece, cutting tool & moving parts

& provide sufficient strength, rigidity & support to the machine

- minimum deflection

because  $\rightarrow$  depend on the support & the material that made of the bed / frame (moment of inertia)

& (inertia values deflections, axis)

(mass moment of inertia & second moment of inertia)

minimum deflection  $\rightarrow$   $\frac{1}{EI}$ ,  $\frac{1}{I}$   $\rightarrow$   $\frac{1}{EI}$   $\rightarrow$   $\frac{1}{I}$

2- power unit  $\rightarrow$  electrical motor, sufficient, high efficiency

3- transmission system  $\rightarrow$  transmit the motion from the power unit to the moving parts

4- spindle  $\rightarrow$  It's the moving part & make sure that the rotation around the center.

$\rightarrow$  either contain the material work piece  $\rightarrow$  turning proc.

$\rightarrow$  or cutting tool material  $\rightarrow$  milling & drilling process.

### 5- work table

If the spindle hold the material workpiece then the holder's table will hold the cutting tool material & vice versa.

& the relative motion between the table & spindle will

cause the final shape of machining & cutting tool.

6- headstock  $\rightarrow$  fixed at the left end of the lathe, holds and rotate the workpiece, support a hollow shaft called spindle

7- tailstock  $\rightarrow$  supporting the tool, like drill bit during the drilling operation on the lathe.

8- carriage  $\rightarrow$  contain parts that hold the tool & control the motion of it like (saddle, cross slides)  $\rightarrow$  provide the motion that is perpendicular to the axis of rotation

9- lead screw  $\rightarrow$  transmit power from the headstock this motion gives the depth of cut in

(Too complex shape)  
we can't work with nano machining in traditional machining process

Limit لحد أقصى

dimension for the cutting tool

planes circumference  
complexity → moderat → low complex shapes

\* We do not reach the desired final shape by one pass  
we remove layer by layer in Machining to reach the desired shape, dimension, finish.

لا نصل إلى الشكل النهائي في دفعة واحدة

Chip removal processes → We have cutting tool (knife)  
it do plastic def. in the workpiece material, then do crack  
و نستخدم كناية بحدود أو كناية

Chipless process → like water jet machining


السرعة ↑

momentum ↑

impulse force  
القوة الدافعة

Machining → Final dimensional accuracy  
→ Final surface finish  
→ special features that we can not do in other processes


Mechanism.




relative motion → friction → temp ↑

If we want to do penetration, I want force  $F_c$

وساكن chip تحركه على سطح ال tool



- 1- the cutting tool exerts a compressive forces on the workpiece
- 2- that ↑ cause the workpiece <sup>material of</sup> plastically deformed
- 3- means the material of the workpiece is stresses beyond the yield point causing the material to deform plastically & shear off
- 3- the plastic flow takes place in a localized region called the shear zone / plane
- 4- this sheared material begin to flow along the cutting tool face in the form of small piece called chip.



atoms shear zone / plastic deformation plane



According to KINEMATICS of the operation

↓ motions without forces

• Flat surfaces

• internal & external surfaces cylindrical & curved surfaces

Rotational → cylindrical or disk-like shape

non rotational → Block like or Plate like shape  
(Prismatic)

### Cutting tool classification

1. single point tool

↳ one ~~dimension~~ dominant cutting edge → not point

↳ point is usually rounded to form a nose radius

example  
(Turning)

2. Multiple cutting edge tools

↳ more than one cutting edge

↳ Motion relative to work achieved  
by rotating.

example  
(twist drill), (milling)




## Machining operation

### 1- turning

the work piece material is connected in the spindle.

circumference  $\approx 8 \times 1 \text{ cm} \approx 8 \text{ mm}$

degree of freedom = rotational motion & rectilinear motion



### 2- Drilling process

the cutting tool move in rotational & rectilinear  
2 degree of freedom for the cutting tool

### 3- End milling

cutting tool

rotational & 2D rectilinear  
3 Degree of freedom system

### 4- slab milling

cutting tool (cutter)

rotational  $\rightarrow$  1 Degree of freedom  
work piece  $\rightarrow$  rectilinear  
1 Degree of freedom

the final shape of the machined part depend on the relative motion between the cutting tool & work piece material  
(degree of freedom for the system)

## Reaming

→ It's like drilling operation, but we don't remove bulk material we just enhance the dimension accuracy to hole already exist  
 OR enhance surface finish for hole already exist.


→ Don't work only if we have ~~the~~ certain Diameter

used to slightly enlarge a hole - provide better tolerance on Diameter, and improve surface finish

\* the ~~accuracy~~ tolerance is ↓ But accuracy ↑↑ surface finish ↑↑ than Drilling


## Milling

→ It's 4 axis machines (4 degree of freedom)  
 → It's multiple cutting edge tool



peripheral milling

axis of the tool is parallel to the surface



face milling

axis of the tool is perpendicular to the surface

slab milling (plane mill) to produce a plain, flat horizontal surfaces


## Broaching

It's look like sawing

In one pass

pull

push



depth of the cut ↑

surface finish ↓ accuracy ↑  
 1 roughing, 2 semi-finishing, 3 finishing

This process is performed using multiple tool cutting, the tool is moved linearly relative to the work

reduce the dimensional accuracy of penetration ↓  
 depth of penetration ↓




**Turning** → It's single tool removes material from a rotating workpiece to form a cylindrical shape.

\* Frame/Bed/structure → (second moment of area/mass moment of inertia)   
 Forces حولها axis الى بسترة

لذلك يكون الارتفاع اقل وسمك اكثر

\* gear Box → power unit   
 وحدة القدرة   
 الحركة

Processing parameter   
 the new surface depend on   
 ↳ Dimensional accuracy for the product   
 ↳ surface quality for the new surface



Internal turning operation → **Boring** → لا يترك عن حوب   
 = حوب الحياطة

Vertical Boring machine

heavy work pieces provide deflection for the spindle

spindle   
 spindle الحياطة   
 machine   
 فستكون لها في الحياطة   
 turning machine   
 الحياطة

relative motion   
 for the work piece material & cutting tool

**Drilling** → used to create a round hole, by means of rotating   
 tool with two cutting edges

torret: to change the active drills

Shapping tool → tool has a linear speed motion, work has occasional Feed motion  
depth of cut

planing → work has a linear speed motion, tool has occasional Feed motion

single


shaping & planing

multiple

sawing  
broaching

Tapping is used to provide internal screw threads on an existing hole

Sawing operations :



Hack saw (the most important saw)

Band saw → for ~~internal~~ cuts

For large cut!

flexibility in cutting → lines  
→ non lines

Disk saw → circular plates

## carbon tool steel

اعادة اليا بهاتوي

ال plastic deformation

ال Forces ال يتاوم كالتا قطع ال

↓ needed power

tools made up of plain carbon steel can be used for machining soft materials such as brass

## HSS

Tungsten 18%

Chromium 4%

Vanadium 1%

widely used for drilling

← replaced the carbon tool steel.

It can resist a high accemidation in heat

600°C (1100°F)

higher mechanical properties

than carbon tool steel

## Carbides

Metals + carbides

cobalt

tungsten

tantalum

titanium

90-93 HRC

mixed together as powder

↓  
compressed to the desired shape

& subjected to heat (temp.)

known as sintering


They can be used at 200-500% greater than the HSS.

They have virtually replaced HSS in high speed & high productivity machining

turning & milling process

cutting tool material

\* It should be stronger (strength) & harder (hardness), from the work piece to withstand forces



\* can resist the sudden cooling thermal shock heat, friction, relative motion

for example we used to work with steels, but there is a problem that steels can't resist the high temperature, so hardness ↓ we use high-speed steel (Alloys) HSS

lose the chemical properties & mechanical      melting in the workpiece material

Very Imp, when used for intermittent cutting → shock loads

\* It should be tough enough → the phases in the cutting process is dynamic.

\* It should be able to resist high temp → red hardness

\* the coefficient of friction between the cutting tool & workpiece material should be as low as possible

total heat → friction

\* Should easily formed to the required cutting shape.



## Ceramics

Aluminum oxide boron nitride powders

mixed together & sintered

at  $1700^{\circ}\text{C}$

- very hard with good compressive strength
- ceramics usually in form of disposal tips



## Functions of cutting fluids

1. It cools the cutting tool & workpiece

This make more accurate production & measurement

Because ~~the~~ that will reduce the temperature, thermal expansion  
- decrease the power consumption accuracy for both cutting tool & work piece

2. It lubricates the cutting tool & reduce the coefficient of friction between chip & tool → increase tool life.

3 - reduce wear

4 - It causes the chips be break up


reduce the contact length ~~in~~ great generation between tool & chip

5 - washes away the chips from tool

6 - prevent corrosion of work piece & machine

7 - reduce thermal distortion of the workpiece.

Frictional power = friction force  $\times$  relative chip velocity




refer to  
detailed structure & features  
include surface roughness,  
texture & any wear

It can also influence the quality of the finished product.

**High cutting temperatures**

- Reduce tool life
- produce hot chips that pose safety hazards to the machine operator
- can cause inaccuracies in part dimensions due to thermal expansion of work material



كل ما يزيد ال thickness  
 حيز العرق اي بتر ال chip  
 فحيز ال friction tool  
 ال tool ال penetration (plastic def.)  
 يعني على جرسين ال elastic strain  
 فحيز ال friction ال area of contact  
 ال سطح (بس ال سطح حيز ال friction  
 ال area of contact  
 ال friction حيز ال


the relation between the thickness (Depth of the cut) & heat generation is that once Depth of the cut  $\uparrow$ , heat generation will increase also because the normal forces will have a higher value

## Properties of cutting fluids

- It should have high specific heat, high heat conductivity  
ليتم تبريد طاقة كالمه جدا من مكان توليد الحرارة في منطقة  
heat تنتقل لو كان في  
موقعه واصغر من درجات الحرارة

- It should possess good lubricating properties to reduce frictional forces & to decrease the power consumption

- It should be odorless, non-toxic, non-corrosive



Additives : Chlorine, Sulfur, Phosphorous, biocides, odorants

## Factor influencing the cutting Machining operation

1. cutting speed, depth of the cut,  $\rightarrow$  affect on the forces, power, temp. rise, type of chip, surface finish & integrity  
(machine properties) Feed - cutting fluids
2. tool angle  $\rightarrow$  As above, flow direction of chip, resistance to wear.
3. Continuous chip  $\rightarrow$  indication of good surface finish, because if so there is a ductile material, appropriate cutting parameters, steady cutting forces  
type of chips
4. Built-up edge chip  $\rightarrow$  indication of poor surface finish & integrity
5. discontinuous chip  $\rightarrow$  desirable for ease of chip disposal (no need to use chip breaker) fluctuation in cutting forces & this will affect the surface finish
6. temperature rise  $\rightarrow$  affect the tool life, crater wear & dimensional accuracy of workpiece may cause thermal damage to workpiece
7. tool wear  $\rightarrow$  Influence the surface finish & integrity
8. Machinability  $\rightarrow$  Related to the tool life, surface finish, forces, power & type of the chip.

## Major types of material removal processes

- 1- cutting
- 2- Abrasive process
- 3- non traditional (Advanced machining process)

Machining operations is a system consisting of \_\_\_\_\_?

- 1- work piece
- 2- cutting tool
- 3- Machine tool
- 4- production personnel

in turning process → the cutting tool (ideal model)

↓  
the deformation in the material  
be in a well defined shear plane

in real cases (sometimes) we don't have well defined shear plane


we will have primary shear zone

**Major independent variables in the cutting process**

- 1- Tool material & coating
- 2- Tool shape, surface finish, and sharpness
- 3- workpiece material & condition
- 4- cutting speed, feed, depth of cut
- 5- cutting fluids
- 6- characteristic of machine tool
- 7- Work holding & fixturing

these factors can be controlled or adjust by the operator


Single point cutting tool  
 ↓  
 have one edge cutting so I should have two planes.



to enhance the properties we did ~~transi~~ smooth transition → curve → nose

the curved region between two cutting edges → yes we do have two edges

but there is just one **active cutting edge**



if perpendicular to workpiece ↓ end cutting edge  
 parallel ↓ side cutting edge

new surface cutting tool  
 flat surface cutting tool


| Depth of the cut   | Thickness of the chip  |
|--|--|
| the perpendicular distance (amount) of material being cut into the workpiece | the final thickness of the chip after it is removed & deformed |
| Affected by Machine settings & tool position                                 | plastic deformation, cutting speed, feed & tool geometry       |



$$t_c > t$$

### Dependent variables in cutting


- 1- Type of chip produced
- 2- force and energy dissipated during cutting
- 3- Temperature rise in the workpiece, the tool & chip
- 4- Tool wear & failure
- 5- surface finish & surface integrity of the workpiece



turning processing  
 circumference ← material  
 chip removed

removed material

↑  
 outer surface  
 و هو موجود



→ surface 3  
 outer surface for  
 the machined part

so we have 2 new surfaces so the energy in these surfaces ↑ very high (unplanned) sys.

that's will cause a shrinkage for the chip length

width more than thickness

و هو موجود

so the chip thickness ↑ depth of the cut

in summary → the plastic deformation & shear strain that material compressed occur as the material flows during the cutting process will cause ↑ depth of cut as it flows over the cutting edge.






$$V t_o = V_c t_c$$

$$V r = V_c = \frac{V \sin \phi}{\cos(\phi - \alpha)}$$

$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos \alpha} = \frac{V_c}{\sin \phi}$$

$$r = \frac{t_o}{t_c} = \frac{V_c}{V}$$




Orthogonal cutting  $\rightarrow$  Merchant Model

$\downarrow$  no cutting ~~edge~~ angle ( $\alpha = 0^\circ$ )

Its two dimensional & the forces involved are perpendicular to each other

Cutting tool has a **Rake angle** of  $\alpha$  & a **relief or clearance angle**



in sin Rule we can say

$$\frac{V}{\sin(90^\circ - \phi + \alpha)} = \frac{V_c}{\sin \phi} = \frac{V_s}{\sin(90^\circ - \alpha)}$$

$V$ : cutting velocity  
 $V_c$ : chip velocity  
 $V_s$ : shear

$$\downarrow r = \frac{t_o \downarrow}{t_c \uparrow} = \frac{\sin \phi}{\cos(\phi - \alpha)}$$

Volume  $i$  = Volume  $f$

$$r < 1$$

$$\text{Shear strain} = \cot \phi + \tan(\phi - \alpha)$$

minimum shear is possible

$$\phi = 45^\circ + \frac{\alpha}{2} = \frac{\beta}{2}$$

$$\rightarrow \phi = 45^\circ + \alpha - \beta \quad (\mu = 0.5 \sim 2) \quad \mu = \tan \beta$$


$\beta$  = friction angle



#### 4. Discontinuous chips

- consist of segments that attached firmly or loosely to each other

Form under these conditions



# Types of chips

## 1. Continuous chips

- formed with ductile materials machined at high cutting speeds and/or high rake angles

- Deformation takes place along narrow shear zone (primary shear zone)


- continuous chips may develop a secondary shear zone due to high friction at the tool-chip interface

## 2. Build-up Edge (BUE) chips

- consist of layers of material from the workpiece that are deposited on the tool tip

- As it grows larger, the BUE becomes unstable & breaks up

BUE can be reduced



## 3. Serrated chips / segmented / non-homogeneous

They are semi-continuous chips with large zones of

low shear strain & small zones of high shear strain


chips have sawtooth-like approach

## Types of chips produced

### 1- Chip curl

↳ chips will develop a curvature (chip curl) as they leave the work piece surface

Factors that affect the chip curl conditions



We can change the rake angle (by putting the chip breaker) either we put a clamp or by changing the tool geometry  
# control chip flow

chip length obtained = 96 mm

Uncut chip length = 240 mm

Rake angle =  $20^\circ$

~~(t)~~ Depth of the cut = 0.6 mm

Horizontal & vertical component of cutting force =  $\frac{2400 \text{ N}}{F_c} \times \frac{240}{F_t}$

1 - shear plane angle

2 - chip thickness

3 - Friction angle

4 - Resultant cutting force

$$1 - \phi = \tan^{-1} \left( \frac{r \cos \alpha}{1 - r \sin \alpha} \right) = \tan^{-1} \left( \frac{0.4 \cos 20}{1 - 0.4 \sin 20} \right) = 23.5^\circ$$

to find  $r \rightarrow L_2 \cdot W \cdot t_2 = L_1 \cdot W \cdot t_1$

$$r = \frac{t_1}{t_2} = \frac{L_2}{L_1} \Rightarrow \frac{96}{240} = 0.4$$

$$2 - 0.4 = \frac{t_o}{t_c} = \frac{0.6}{t_c} = 1.5 \text{ mm}$$

$$3 - \lambda = \tan^{-1}(0.48) = 25.64^\circ$$

$$\mu = \frac{F_t \cos \alpha + F_c \sin \alpha}{F_c \cos \alpha - F_t \sin \alpha} = \frac{240 \cos 20 + 2400 \sin 20}{2400 \cos 20 - 240 \sin 20} = 0.48$$

$$R = \sqrt{F_c^2 + F_t^2} = \sqrt{2400^2 + 240^2} = 2412 \text{ N}$$

rake angle =  $10^\circ$

$$\mu = 0.85$$

$$t = 2.5 \text{ mm}$$

$$\text{(Feed)} \quad d = 1.5 \text{ mm}$$

$$V_c = 40 \text{ m/min}$$

$$W = 15 \text{ mm}$$

$$\text{(Shear strength)} \quad \tau = 650 \text{ N/mm}^2$$

$$1- \quad r = \frac{t}{t_c} = \frac{1.5}{2.5} = 0.6 \quad \frac{\text{depth of cut}}{\text{Thickness}}$$

2- shear angle!

$$\phi = \tan^{-1} \left( \frac{r \cos \alpha}{1 - r \sin \alpha} \right) = \tan^{-1} \left( \frac{0.6 \cos 10^\circ}{1 - 0.6 \sin 10^\circ} \right) = 33.4^\circ$$

3- Shear force

$$F_s = \tau (A)$$

$$A \sin \phi = A'$$

$$A \sin \phi = \text{width} \times \text{depth of cut}$$

$$F = 650 \times 40.873$$

$$A = \frac{15 \times 1.5}{\sin(33.4)} =$$

$$= 26.57 \text{ N}$$

4- friction angle

$$\lambda = \tan^{-1} \mu = \tan^{-1} (0.85) = 40.36^\circ$$

5- cutting force

$$F_c = R \cos(\lambda - \alpha)$$

$$60.088 \cos(40.36 - 10)$$

$$= 51.85 \text{ kN}$$

$$R = \frac{F_s}{\cos(\phi + \lambda - \alpha)}$$

$$= \frac{26.57}{\cos(33.4 + 40.36 - 10)}$$

$$= 60.088 \text{ kN}$$

$$R = 60.088 \text{ kN}$$

$$\text{(Tangential Force)} \quad F_t = R \sin(\lambda - \alpha)$$

$$60.088 \sin(40.36 - 10)$$

$$= 30.37 \text{ kN}$$

$$6- \text{ power consumed} = F_c V_c = 51.85 \times 40 = 34.57 \text{ kW}$$

given





Orthogonal → the direction of the tool velocity & the tool cutting edge perpendicular  
→ shear force acts on a smaller area

Oblique → the cutting edge of the tool is at angle less than  $90^\circ$  to the direction of tool travel  
→ shear force act on larger area  
↓  
tool have longer life

shaving & skiving

$$F = F_T + F_C \tan \alpha \cdot \frac{\sin \phi}{\cos \phi}$$





$$\left. \begin{array}{l} \text{shear force } F_s = F_c \cos \phi - F_T \sin \phi \\ \text{Normal force } F_n = F_c \sin \phi + F_T \cos \phi \end{array} \right\}$$

$$\text{Friction force } F = F_c \sin \alpha + F_T \cos \alpha$$

$$N = F_c \cos \alpha - F_T \sin \alpha$$

$$F_s = R \cos(\phi + \beta - \alpha)$$

$$F_n = R \sin(\phi + \beta - \alpha)$$

$$F_c = R \cos(\beta - \alpha)$$

$$F_T = R \sin(\beta - \alpha)$$

$$F = R \sin \beta$$

$$N = R \cos \beta$$

$$\tan \beta = \mu = \frac{F}{N} = \frac{F_T + F_c \tan \alpha}{F_c - F_T \tan \alpha}$$

$$\beta = \tan^{-1}(\mu)$$

$$\text{shear strain } \phi = \cot(\phi) + \tan(\phi - \alpha)$$

$$P_c = F_c \times V$$


$$\text{shear stress } \frac{F_s}{\text{W.T}}$$

$$\text{normal stress } \frac{F_n}{\text{W.T}} = \frac{F_n \sin \phi}{\text{W.T}}$$






$F_t$ : axial feed force  
(Thrust force)



$F_c$ : tangential force  
(cutting=)



$F_s$  (shear force)

$F_n$  (normal force)





$$3 - \tau = \frac{F_s}{w \cdot t} \sin \phi$$

$$F_s = R_c \cos \phi - F_t \sin \phi = 244.995 \text{ N}$$

$$\Rightarrow \frac{244.995 \approx 240}{2.5 \times 0.13} \times \sin(28.41)$$

$$= 359 \text{ MPa}$$

$$4 - \gamma = \cot(\phi) + \tan(\phi - \alpha)$$

$$= \frac{\cos(28.41)}{\sin(28.41)} + \tan(28.41 - 5) = 2.51$$

$$5 - V_s = \frac{V}{\cos(\phi)}$$

$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos(\alpha)} \rightarrow V_s = 7.38$$

6 - specific energy

$$u_s = \frac{F_s}{w \cdot t}$$

$$= 760.3 \text{ N/mm}^2$$

$$t_c = 0.13 \text{ mm}$$

$$W = 2.5 \text{ mm}$$

$$\alpha = -5^\circ$$

$$V = 2 \text{ m/s}$$

$$t_c = 0.23 \text{ mm}$$

$$F_c = 430 \text{ N}$$

$$F_t = 280 \text{ N}$$

$\phi = ?$  Don't use the approximation eq.

$$\phi = \tan^{-1} \left( \frac{r \cos \alpha}{1 - r \sin \alpha} \right) = \tan^{-1} \left( \frac{0.57 \cos(-5)}{1 - 0.57 \sin(-5)} \right)$$
$$r = \frac{0.13}{0.23} = 0.57$$
$$= 28.41^\circ$$

Determine the friction coef.

$$\mu = \tan(\beta)$$

$$R = \sqrt{280^2 + 430^2} = 513.13 \text{ N}$$

given  $\alpha, \phi = 28.41^\circ, -5^\circ, 28.41^\circ$

$$\beta = \tan^{-1} \left( \frac{F}{N} \right)$$

$$F = 430 \sin(-5) + 280 \cos(-5) = 241.46 \text{ N}$$

$$R = \sqrt{F^2 + N^2} = \sqrt{241.46^2 + N^2} = 513.13$$

$$N = 452.77 \text{ N}$$

$$\beta = \tan^{-1} \left( \frac{241.46}{452.77} \right) = 28.07^\circ$$

If another way:-

$$F_c = R \cos(\beta - \alpha)$$

$$430 = 513.13 (\beta - (-5))$$

$$\beta = 28.07$$

معطى  $F_c = 430$  و  $R = 513.13$

$$\cos^{-1} \left( \frac{430}{513.13} \right) = \beta - (-5)$$

$$\beta = \tan^{-1} \left( \frac{F_t}{F_c} \right)$$



$C_1$  (cutting speed = 375 ft/min  
Tool Life = 5.5 min

$$n = 0.137$$

$C_2$  (expected tool life  $T_2 = ?$   
cutting speed = 300

$$C = VT^n$$

$$V_1 T_1^n = V_2 T_2^n$$

$$375 (5.5)^{0.137} = 300 (T_2)^{0.137}$$

$$T_2 = 28.04 \text{ min}$$

$$375 \times 5.5^{0.137} = C$$

$$4737 = C$$

$$\frac{300 T^{0.137}}{300} = \frac{4737}{300}$$

$$0.137 \times \ln T = \ln \left( \frac{4737}{300} \right)$$

$$\ln T = \frac{0.4567}{0.137} = 28.04 \text{ min.}$$

$$\text{cutting force} = 1470 \text{ N}$$

$$\text{Thrust force} = 1589 \text{ N}$$

$$\alpha \text{ rake angle} = 5^\circ$$

$$W = 5 \text{ mm}^2$$

$$\text{Thickness before cut} = 0.6$$


$$\text{Thickness ratio} = 0.38$$

$$r = \frac{t}{t_c}$$

$$0.38 = \frac{0.6}{t_c}$$

$$t_c = 1.58$$

a) shear strength



$$\tau = \frac{F_s}{W \cdot t}$$

$$F_s = F_c \cos \phi - F_r \sin \phi$$

$$1470 \cos(21.38) - 1589 \sin(21.38) = 789.52 \text{ N}$$

$$\phi = \tan^{-1} \left( \frac{r \cos \alpha}{1 - r \sin \alpha} \right) = 21.38^\circ$$

$$\tau = \frac{789.52 \sin(21.38)}{5 \times 0.6} = 95.9 \text{ MPa}$$

b) coeff. of friction

$$\mu = \tan \beta$$

$$F_c = R \cos(\beta - \alpha) \Rightarrow 1470 = 2164.7 \cos(\beta - 5)$$

$$R = \sqrt{1470^2 + 1589^2} = 2164.7 \text{ N} \quad \cos^{-1} \left( \frac{1470}{2164.7} \right) = \beta$$

$$= 1.291$$

$$\beta = 52.23^\circ$$

if not orthogonal

$$\phi = 45 + \frac{\alpha}{2} - \frac{\beta}{2} \quad \beta = 52.24$$

$$\mu = \tan \beta = 1.29 \checkmark$$



orthogonal cutting op.

$$t_o = 0.13$$

$$V = 120 \text{ m/min}$$

$$\alpha = 10^\circ$$

$$W = 6 \text{ mm}$$

$$t_c = 0.23 \text{ mm}$$

$$F_c = 500 \text{ N}$$

$$F_t = 200 \text{ N}$$

calculate the percentage of the total energy that goes into overcoming friction at the tool chip interface?

$$\frac{M_f}{M_E} = \frac{F_f}{M_f + M_s}$$

$$\frac{F_{Vc}}{F_{cV}} = \frac{F_r}{F_c}$$

$$M_s = \frac{F_s V_s}{W t_o V}$$

material removal rate

$$F = F_c \sin \alpha + F_t \cos \alpha$$
$$= 500 \sin 10 + 200 \cos 10 = 283.78 \text{ N}$$

$$r = \frac{0.13}{0.23} = 0.57$$

$$\frac{M_f}{M} = \frac{283.78 \times 0.57}{6 \times 0.13}$$

$$\frac{283.78 \times 0.57}{500}$$

$$M_f = 32.35 \%$$




## Temp. distribution

- The temp. increase with cutting speed
- chip can become red hot & create a safety hazard
- The chip carries away most of the heat generated

Higher cutting speeds  $\rightarrow$  better heat dissipation via the chip  
reducing thermal damage to  
the work piece & tool

### Temperature rise



$$T = \frac{0.000665 (Y_f)^2 \sqrt{Vt_0}}{PC \sqrt{K}}$$

$Y_f$  ← flow stress  
 $V$  → velocity  
 $t_0$  → depth of the cut  
 $P$  ← heat capacity  
 $K$  → thermal conductivity

$$T_{mean} \propto V^{0.75} f^{0.75}$$

$$= 1.2 \times 10^{-4} \text{ } \dots$$

| Primary zone (shear zone) | Secondary zone (Tool-chip interface)  | Zone three (between interface between the surface of tool & new surface) |
|---------------------------|---|--|
|                           | out ↑<br>length of contact<br>> int<br>friction ↓<br>even though we have use coolant because there is no gap to enter | there is coolant effect & high rate of cut.                              |

$$D = 12.7 \text{ mm}$$

$$d = 60 \text{ mm} \quad \theta = 118^\circ$$

$$V_e = 25 \text{ m/min}$$

$$\text{feed} = t_e = 0.3$$

$$V = 60 \frac{\text{m}}{\text{min}} \times 60 \quad V = \pi D N$$

$$60 = \pi (4) N$$

$$N = \frac{60}{\pi (4 \times 0.0254)}$$

$$1-22-2$$

$$= 187.9 \text{ rpm}$$

$$i = 20^\circ, \text{ tool tipped}$$

$$\alpha_n = 10^\circ$$

$$W = 0.2 \text{ inch}$$

$$t_e = 0.1 \text{ in}$$

$$\gamma_s = 50,000 \text{ lb/in}^2$$

$$r = 0.4$$

$$N = 400 \text{ rpm}$$

$$\alpha_e = \sin^{-1}(\sin^2 i + \cos^2 i \sin \alpha_n)$$

$$= 15.68^\circ$$

$$\gamma_s = \frac{F_s}{W t_e} \sin \phi$$

$$50,000 = \frac{F_s}{0.2 \times 0.1} \sin \phi$$

$$\phi = \tan^{-1} \left( \frac{r \cos \alpha_e}{1 - r \sin \alpha_e} \right) = \tan^{-1} \left( \frac{0.4 \cos 15.7}{1 - 0.4 \sin 15.7} \right)$$

$$= 23.35^\circ$$

1) cutting forces

2)  $P_{\text{spindle}}$

3) Power shear =  $F_s V_s$

$$P = F_c V$$

$$\gamma_s = \frac{F_s}{W t_e} \sin \phi \rightarrow F_s = 2523 \text{ lb}$$

$$\phi = 45^\circ + \frac{\alpha}{2} = \frac{\beta}{2}$$

$$\beta = 58.98^\circ$$

$$F_s = R \cos(\phi + \beta - \alpha)$$

$$2523 = R \cos(23.35 + 58.98 - 15.7)$$

$$R = 6365.64 \text{ lb}$$



السؤال اي صطوله كوتور  
مستان كيلو

$$\text{Depth of cut} = t_1 = 0.13 \text{ mm}$$

$$\text{Width} = w = 2.5 \text{ mm}$$

$$\text{rake} = \alpha = -5^\circ$$

$$V = 2 \text{ m/s}$$

$$t_c = 0.23 \text{ mm}$$

$$F_c = 430 \text{ N}, F_t = 280 \text{ N}$$

$$1 - \phi = \tan^{-1} \left( \frac{r \cos \alpha}{1 - r \sin \alpha} \right) = \tan^{-1} \left( \frac{0.57 \cos(-5)}{1 - 0.57 \sin(-5)} \right) = 28.4^\circ$$

$$r = \frac{t_1}{t_2} = \frac{0.13}{0.23} = 0.565 \approx 0.57$$

$$2 - \mu = \tan^{-1}(\beta)$$

$$= \frac{F_t + F_c \tan \alpha}{F_c - F_t \tan \alpha}$$

$$= \frac{280 + 430 \tan(-5)}{430 - 280 \tan(-5)}$$

$$= 0.53$$

$$R = \sqrt{F_c^2 + F_t^2}$$

$$= \sqrt{430^2 + 280^2}$$

$$= 513.13 \text{ N}$$

$$F_c = R \cos(\beta - \alpha)$$

$$7 - M_f = \frac{F_r}{w t_0}$$

$$792.5 = \frac{0.57 \times F}{2.5 \times 0.13}$$

$$8 - M_s = \frac{F_s V_s}{w t_0 V} = 904.8$$

$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$= 430 \cos(28.4) - 280 \sin(28.4) = 245.07 \text{ N}$$

$$= \frac{245.07}{2.5 \times 0.13} \sin(28.4) = 358.66 \text{ N/mm}^2$$

$$4 - \epsilon = \cot(\phi) + \tan(\phi - \alpha) = 2.5$$

$$5 - \frac{V_{cut}}{\sin \phi} = V_c = ?$$

$$\frac{V}{\sin(90 - \phi + \alpha)} = \frac{V_c}{\sin \phi}$$

$$6 - \frac{V_s}{\sin(90 - \alpha)} = \frac{V}{\sin(90 - \phi + \alpha)} = \frac{V_c}{\sin(28.4)}$$

$$V_s = 2.4 \text{ m/s}$$



$$V_c = 1.14 \text{ m/s}$$

### Allowable wear land

- cutting tools need to be replaced when:
  - 1- surface finish of the machined workpiece begins to deteriorate
  - 2- cutting forces increase significantly
  - 3- Temp. rises significantly

### Example 21.3

cutting speed is  $60 \text{ m/min}$ , tool life is  $40 \text{ min}$

$$\text{travel distance} = 60 \times 40 = 2400 \text{ m}$$

when cutting speed is increased to  $120 \text{ m/min}$

tool life reduced  $5 \text{ min}$  & travel  $600 \text{ m}$

- Crater wear occurs on the rake face of the tool

production rate

$$5 \times X = 40$$

$$X = 8$$

$$\text{then } 600 \text{ m} \times 8 = 4800$$

$$4800 > 2400$$

part

factors affect (influence) crater wear

- 1- temperature at the tool-chip interface
  - 2- the chemical affinity between the tool & workpiece material
- Diffusion rate increases with increasing the temp.  
crater wear increase as temp. increase

surface quality { surface finish & dimensional accuracy of machined part, geometric features  
surface integrity & microstructure of the new surface (machined part) & material property.

## Stainless steel

Austenitic

BCC

difficult  
to machine

(300 series)

ferritic

FCC

good  
machinability

(300 series)

Martensitic

deformed  
structure

Abrasive

(400 series)


## Thermally assisted machined

(hot machining) → a source of heat is focused onto an area just ahead of the cutting tool


Adv-

- ↳ Reduce cutting force
- ↳ increase tool life
- ↳ Higher material-removal rate
- ↳ Reduced tendency for vibration & chatter

## Factors influencing the surface integrity



## Machinability



good Machinability indicate good surface finish & surface integrity, long tool life, & low forces & power req.

## Machinability

### ↓ Ferrous Metal

- Steels
  - If a carbon steel is too ductile that will cause to produce build up edge → poor surface Finish
  - If too hard, It can cause abrasive wear because of presence of carbides in the steel

- Lead steel
  - high percentage of lead solidified at the tip of manganese sulfide inclusions

- Calcium-deoxidized steels
  - oxide flakes of calcium silicates (CaSiO) that reduce the strength of the secondary shear zone & decrease tool chip interface friction & wear.

effect of various elements in steels

presence of aluminum & Silicon as they combine with oxygen → aluminum oxide and silicate that are abrasive and hard → ~~reduce~~ increase tool wear

### ↓ Non Ferrous metal

Aluminum & Magnesium

EASY TO MACHINE with good surface finish & prolonged life

Beryllium

↳ machining in a controlled environment

cobalt-based alloys

↳ requires sharp, abrasion-resistant tool material & low feed & speeds

copper

↳ difficult to machine because of build up edge form

Titanium → very poor thermal conductivity

Tungsten → brittle, strong & very abrasive

reduce Machinability

& increase



# (Chapter 24)

## Milling

↳ a process in which a rotating multi-tooth cutter removes material while traveling along various axes with respect to the workpiece.

good surface finish / great accuracy

### types of milling



When the width of the cutter is greater than the width of the workpiece material (Slab milling)

cutter is longer than the width of the cut.

### • Ball-End Milling

↳ For machining complex 3D cutter shapes

↳ provides smooth finishes due to its rounded cutting edge

### • CNC Milling of sculptured surface



$N$ : rotational speed (rpm)

$f$ : feed per tooth mm/tooth

$$= \frac{v}{Nn} \rightarrow \text{linear speed of the work piece or feed rate}$$

$D$ : cutter diameter

$n$ : no. of teeth

$v$ : linear speed of the workpiece or the feed rate  $\frac{\text{mm}}{\text{min}}$  (in/min)

(cutting speed)

$V$ : surface speed of the cutter  $= \pi D N$

$L$ : length of the cut

$$t: \text{cutting time} = \frac{(L + L_c)}{v}$$

$L_c$ : extent of the cutters first contact with workpiece  $L_c = \sqrt{Dd}$

$MRR = w d v$  width of the cut  
 $\text{Torque} = F_c \frac{D}{2}$  (N.m) if slab milling length of the cutting edge width of the workpiece then we do  $= \frac{w}{n \text{ width of the workpiece}}$

$\text{Power} = \text{Torque} \cdot \omega \rightarrow 2\pi N$  (kW or hp)

Example 24.1 in slides

- $L = 300 \text{ mm}$ ,  $100 = W$
- $f = 0.25 \text{ mm/tooth}$
- $d = 3 \text{ mm}$
- $D = 50 \text{ mm}$
- $n = 20$
- $N = 100 \text{ rpm}$

$$MRR = \frac{L W d}{t} = w d v = 100 \times 3 \times 500 = 150,000 \text{ mm}^3/\text{min}$$

$$f = \frac{v}{Nn} \rightarrow 0.25 = \frac{v}{20 \times 100}$$
  
 $v = 500 \text{ mm/min}$

$\text{Torque} = \frac{F_c D}{2}$   
we don't have any forces

so far the table (given that we have annealed mild steel)

$$U = 3 \text{ W} \cdot \text{s} / \text{mm}^3$$
  
second

$$U = 3 \times \frac{150000}{60} = 7500 \text{ W}$$

$$\text{Torque} = \frac{\text{power}}{\omega} = \frac{7500 (60)}{2\pi (100)} = 716.197 \text{ N} \cdot \text{m}$$

$$t = \frac{(L + L_c)}{v} = \frac{300 + \sqrt{50 \times 3}}{500} = 0.624 \text{ min} = 37.4 \text{ sec}$$

## Milling Operations

### conventional / UP milling

the direction of the rotation of the cutter & direction of the workpiece is opposite to each other

- Maximum chip thickness is at the end of the cut

• Adv: tooth engagement is not a function of the work piece surface  
(Cutting starts with less force)

- Disadv: The cutter can cause the machine to shake (chatter) making it harder to get a precise cut.

- the cutting process is smooth because the cutter gradually (bites) into the material

- the workpiece has a tendency to be pulled upward, so we must clamp the cutter tightly

→ that means it's good for dirty, scale & rust surfaces because ~~the tool~~ it won't damage the tool because the cutting starts with low forces (smooth start).

### Climb milling

(DOWN Milling)

move in the same direction

(CW)

- cutting starts at the surface of the workpiece.

- Downward compression of the cutting forces hold the workpiece in place

- Because of resulting high impact forces when teeth engage the workpiece

↓  
this operation must have

a rigid setup

Backlash must be eliminated in the table feed machine

- Not suitable for machining workpiece that have surface scale

## Q2 / Activity 2

peripheral Milling

$$L = 600 \text{ mm}$$

$$W = 40 \text{ mm}$$

$$D = 60 \text{ mm}$$

$$n = 10$$

$$V = 60 \text{ (m) / min}$$

$$f = 0.15 \text{ mm / tooth}$$

$$d = 5 \text{ mm}$$

$$\text{MRR} = ?$$

~~$$\text{MRR} = w d v = 40 \times 5 \times 60 \times 10^3 = 12$$~~

$$\text{MRR} = w d v$$

$$\frac{V}{Nn} = f \quad \quad \quad V = 0.15$$
$$N = \frac{V}{\pi D} = \frac{60 \times 10^3}{\pi (60)} \rightarrow \text{to convert it to mm} = 318.31$$

$$\text{Better } V = \frac{60}{\pi (60 \times 10^3)} = 318.31$$

to convert it to (m)

$$V = 477.465 \text{ mm / min}$$

$$\text{MRR} = 40 \times 5 \times 477.465 = 95493 \text{ mm}^3 / \text{min}$$

$$t = \frac{Lwd}{\text{MRR}} = \frac{600 \times 40 \times 5}{95493} = 1.257$$

$$\frac{L+L_c}{v} = \frac{600 + \sqrt{60 \times 5}}{477.465} = 1.29$$

A

**Face Milling**  $\rightarrow L_c = \frac{D}{2}$  (Bad quality)

$\rightarrow$  lead angle on underformed chip Thickness in face Milling

- As the lead angle  $\uparrow$  underformed chip thickness  $\downarrow$  length of  $\uparrow$   
Range = 0-45  $\downarrow$   $\uparrow$   
(chip width) (contact)
- As the lead angle decreases there is a smaller vertical force comp. (axial force)  $\rightarrow$  the process less demanding on the cutting tool
- The cross-sectional area of the underformed thickness remains constant

| High lead angle  | Low lead angle  |
|--|---|
| <ul style="list-style-type: none"><li>• underformed thickness of the chips <math>\downarrow</math></li><li>• length of contact <math>\uparrow</math> (may increase)</li><li>• Reduces the vertical force component, improving Tool life &amp; surface finish</li></ul> | <ul style="list-style-type: none"><li>• <math>\uparrow</math> underformed chip thickness</li><li>• <math>\downarrow</math> length of contact</li><li>• high vertical force component</li><li>increase stress on the tool &amp; workpiece.</li></ul> |

$\neq$  entry & exit of the cutter

- entry  $\rightarrow$  the cutter initially engages the workpiece, and the forces build up gradually
- exit  $\rightarrow$  the forces reduce, but ~~undesirable effects~~ improper exit angles can cause undesirable effects such as poor surface finish or tool damage.

**End milling**

- $\rightarrow$  hemispherical ends (bull-nose mills) for the (3D) production of sculptured surfaces, such as dies & molds
- $\rightarrow$  can produce a variety of surfaces at any depth, curved, stepped & pocketed

6 - Back striking → Dull cutting tool  
↳ negative tool angle  
↳ tilt in the cutter spindle

7 - Chatter marks → insufficient stiffness of the sys.  
↳ external vibration  
↳ feed, width, depth of the cut too large.

8 - Burr formation → Dull cutting edges.  
↳ incorrect angles of entry or exit  
↳ incorrect insert shapes  
↳ feed & depth of the cut too high

9 - Breakout → lead angle too low  
↳ incorrect angle of entry & exit  
↳ incorrect cutting edge geometry  
↳ ~~insert~~ feed & depth of cut too high

Burr formation → It's a common defect when the cutting tool doesn't cleanly exit the material

Large Breakout → when the cutting tool exits at an unfavorable angle or with excessive force

Small Breakout → when ~~the~~ increasing the lead angle of the cutter, **BREAKOUT SIZE REDUCED**

Q. Find the time

$$D = 10.7 \text{ mm}$$

$$L = 50 \text{ mm}$$

$$V = 35 \text{ m/min} \rightarrow N = \frac{V}{\pi D} = \frac{35 \times 10^3}{\pi (10.7)} = 1041.2 \text{ RPM}$$

$$f = 0.4 \text{ mm/rev}$$

$$t = ??$$

$$t = \frac{L + L_c}{f N}$$

$$f = \frac{V}{N D}$$

$$\rightarrow v = 1041.2 \times 0.4$$

$$= 416.48 \text{ mm/min}$$

$$t = \frac{L}{f N} = \frac{50}{0.4 \times 1041.2} = 0.12 \text{ min} = 7.2 \text{ sec.}$$

### Troubleshooting guide for Milling operations

1. Tool Breakage

- Tool material lacks toughness
- improper tool angles
- machining parameters too high

2. excessive tool wear

- improper cutting fluids
- improper tool material
- improper tool angles

3. Rough surface finish

- Feed per tooth is high
- too few teeth on the cutter
- tool chipped or worn
- built up edge
- vibrations & chatter


4. Tolerance too broad

- lack of spindle & work holding stiffness
- excessive temp. rise
- dull tool
- chips clogging cutter

5. work piece surface burnish

- Dull tool, depth of cut too low
- radial relief angle too small

# D. Adv. of machin's



改善

KAIZEN


## THE BASIC COMPONENTS OF MILLING MACHINES

- **Worktable** → in which the work piece is clamped using T-slots  
The table moves longitudinally relative to the saddle (back & forth)
- **Saddle** → support the table & can move in the transverse direction. (side to side)
- **Knee** → support the saddle & gives the table vertical movement so that the depth of the cut can be adjusted & work pieces with various heights can be accommodated.
- **overarm** → used on horizontal machines, adjusts for different arbor length (hold longer tools)
- **Head** → contains the spindle & the cutter holders, & it can be swivel & adjust for tapered surfaces. & adjust its angle and direction position for cutting.

**Bed-type Milling Machine** → heavy work pieces  
Because the bed & <sup>work</sup>table are fixed

### CNC vertical-spindle milling machine


**AXIS** → relative motion that can be done between workpiece & cutting tool material



6 ← درجات الحرية

درجات الحرية  
 freedom  
 حرية الحركة  
 تكون في المحاور الثلاثة


### Why Machining is Imp.?






## Drilling

is the operation of producing circular hole in the workpiece by rotating cutter



- The drilling operation can also be accomplished in lathe in which the drill is held in tailstock & the work is held by the chuck
- The most common Drill is the twist drill
- the Drilling machine is the simplest & accurate machine used in production shop in which the work piece is held stationary (clamped in position) & the drill rotates to make a hole.

## Types of Drilling Machine



### UP-right Drilling Machine

The table moves vertically & radially

Radial Drilling Machine → It's the largest & most versatile type of drilling medium to large & heavy workpieces.

## Tool holding devices

for holding the drill spindle

- by directly fitting in the spindle hole
- by using drill sleeve
- by using drill socket
- by using drill chuck → most commonly used in portable drills.

## Types of cutter

### 1- Reamers

Multi tooth cutter to enhance the surface finish for existing hole  
Accuracy of  $0.0005 \text{ mm}$  can be achieved

### 2- Boring Tool

Single point cutting tool

Accuracy of  $0.005 \text{ mm}$  can be achieved

### 3- Countersinks

special angled cone shaped enlargement at the end of the hole  
cutting edges at the end of conical surfaces

### 4- Counter Bore Tool

special cutter uses a pilot to guide the cutting action

two most common types

HSS Drill

18-4-1  
↑ tungsten    ↓ chromium    → vanadium

Low cost

Other types

- ↳ solid carbide drill
- ↳ TIN coated drills

Carbide-tipped drills

high production rate & in

**CNC**

types of Drills

Twist drill

step drill

produces holes of two or more different diameter

↳ cone drill used to make an existing hole bigger

straight-flute


spade

gun

Drilling operation

Drilling center hole

Twist Drill → p80



slide 11

\* precautions for Drilling machine

- 1 - Lubrication
- 2 - Machines should be cleaned after use
- 3 - chips should be removed using brush
- 4 - Machines should be lightly oiled to prevent from rusting

\* Safety precautions

see slide 27

Q1) Activity 2

$$D = 10.7 \text{ mm}$$

$$d = 60 \text{ mm}$$

$$\theta = 118^\circ$$

$$V = 35 \text{ m/min}$$

$$f = 0.4 \text{ mm/rev}$$

$$V = \pi D N$$

$$d = \frac{D}{2}$$

$$MRR = \frac{\pi D^2}{4} \times f \times N$$

$$t = \frac{L}{f N}$$

$$t = \frac{L}{f N}$$

$$N = \frac{V}{\pi D} = \frac{35 \times 10^3}{\pi (10.7)} = 1041.2 \text{ rpm}$$

$$d = \frac{D}{2} = \frac{10.7}{2} = 5.35 \rightarrow d = \frac{D}{2} \cdot \tan\left(\frac{\text{Point Angle}}{2}\right)$$

$$L = 60 - 5.35 = 54.65$$

$$d = 8.9$$

$$t = \frac{54.65}{0.4 \times 1041.2} = 0.1312 \text{ min}$$

$$L = 60 + 8.9 = 51.5 \text{ mm}$$

$$MRR = \frac{\pi (10.7)^2}{4} \times 0.4 \times 1041.2 = 37449.98 \text{ mm}^3/\text{min}$$

OR  $D = 10.7$   
 $L = 60$

$$t = \frac{60}{0.4 \times 1041.2} = 0.144 \text{ min}$$

$$MRR = \frac{\pi (0.7)^2}{4} \times 0.4 \times 1041.2 = 8.6 \text{ sec } 0.144 \text{ min}$$

$$37,450 \text{ mm}^3/\text{min}$$

### → Abrasive disk sawing

- uses an abrasive wheel to cut through hard ~~metals~~ materials
- used for → wet cutting
  - ↳ dry cutting → up to 80 m/s
- Better finish & accuracy than steel friction blades.

### → Band saw

↳ uses a long, continuous band with teeth on one edge.

Can handle → straight  
↳ curved cuts.

→ Band friction cutting → operates at high speeds (15 - 75) m/s

↳ used for thin ferrous metals & some thermoplastic material

→ Diamond band cutting → diamond-impregnated band



↳ used to cut hard materials like glass, ceramics, carbide, dies & hard semiconductor materials

↳ for finishing & polishing use a file band instead of saw band.

# LINEAR METAL CUTTING

## ACTIONS & SAWING, BROACHING & SHAPING


### \* Sawing



\* Cutting speed

- for ferrous metal 0.1 - 0.4 m/s
- for nonferrous metal 1 - 20-3 m/s
- ↓
- these metals tend to stick to the blade due to friction & heat

cutting ability → dependent on the metal structure, & its melting characteristics



## Advantages for mass production



- 1- roughing & finishing in one pass
- 2- short cutting time
- 3- Versatility → internal surfaces  
↳ external =
- 4- high production tolerance
- 5- good surface finish
- 6- Burnishing effect

## Disadvantages



- 1- high tool cost
- 2- not advisable for short run
- 3- Rigid part support needed.
- 4- limited to single operation



# Broaching


removal of material in one stroke

High rake angle

↓  
high quality

↓  
lower friction

Stages:



## types of broaching operation

pull Broaching

↓  
longer cuts

Push Broaching

↓  
shorter cuts

the Broacher is pushed through the workpiece

continuous Broaching

↓  
• high speed production

• work is moved continuously against the stationary Broaches

Key way

## type of machine

vertical

↓  
surface broaching


Horizontal

↓  
internal & surface broaching of small - and medium - size parts

Continuous tunnel broaching Machine

↓  
surface broaching

## Components of a shaping Machine



## Mechanism of motion conversion

The shaping machine converts the **rotational motion** (from the motor)

↳ **gear mechanism**

↓  
Transfers the motor's rotational energy to the shaping mechanism

↓  
**translation motion** (reciprocating motion of the ram)

\* **fly wheel**

stores the rotational energy & maintains a smooth operation by reducing fluctuations in the ram's motion

→ **bigger FLYWHEEL**  
is used for higher moment of inertia which stabilizes the motion & handling larger impact forces during the cutting process.

\* **Crank & lever system**

converts the rotational motion of the motor & flywheel into a linear motion.

**Shapers** → Machine tool that uses a reciprocating ~~tool~~ motion for a straight line cut

It's a single point cutting tool

The work piece is stationary, while the cutting tool moves in a straight line back & forth

shapers are ideal for machining flat surfaces.

### Types of shapers

horizontal

vertical

heavy cuts

Internal cutting

commonly used

suitable for die work,

in rail road shops

metal molds, metal patterns

for shaping large components.

Adv: little vibration or chatter

There is two type of conditions → orthogonal shaping  
→ oblique shaping

### Key points

#### 1- cutting tool motion

→ The cutting tool is mounted on a ram.

→ The ram is moved in a ~~cutting~~ reciprocating motion

Forward stroke

Return stroke

cuts the material at  
a velocity  $V$

Moves back quickly  
without cutting  
the velocity is higher  
than the cutting stroke.

#### 2- cutting velocity

The velocity is not constant throughout the cutting stroke

- Starts at zero at the beginning of the stroke
- Increases to maximum in the middle of the stroke
- gradually decreases back to zero at the end of the stroke

سؤال حلوه  
2/

surface 600 x 800 mm

$$V_c = 8 \text{ m/min}$$

$$i = 4$$

f = 2 mm / double stroke

the clearance = 70 mm

cutting total time?

$$\text{Total length} = L + C_1 + C_2$$

$$= 600 + 70 + 70 = 740 \text{ mm}$$

$$\text{cutting time} = \frac{L}{V} = \frac{740 \text{ mm} \times 60}{8 \text{ m/min} \times 10^3} = 5.55 \text{ sec}$$

$$\text{Return time} = \frac{\text{cutting time}}{\text{From ratio} \rightarrow 4} = \frac{5.55}{4}$$

$$\text{total time for one stroke} = t_c + t_r = 6.94 \text{ sec}$$

$$\text{Total strokes required} = \frac{\text{width of plate}}{\text{feed}} = \frac{800}{2} = 400$$

$$\text{cutting total time} = \text{Total strokes} \times \text{total time req for one stroke} \\ = 400 \times 6.94 = 2775 \text{ sec} = 46.25 \text{ min}$$

example 2

$$L = 250 \text{ mm}$$

$$f = 2 \text{ mm/stroke}$$

$$W = 150 \text{ mm}$$

$$C = 25 \text{ mm}$$

$$\frac{\text{cutting}}{\text{return}} = \frac{3}{2}$$

$$d = 4 \text{ mm}$$

$$V_c = 21 \text{ m/min}$$

find the total machining time & MRR?

$$L_{\text{Total}} = 250 + 25 + 25 = 300 \text{ mm}$$

$$t_c = \frac{L}{V} = \frac{300 \times 10^3}{21 \text{ m}} \times 60 = 0.857 \text{ sec}$$

$$\text{MRR} = wdV \\ = 150 \times 4 \times$$

$$t_r = \frac{0.857}{3} \times 2 = 0.571 \text{ sec}$$


$$\text{Total time} = 0.857 + 0.571 = 1.428 \text{ sec}$$

$$\text{Total strokes} = \frac{150}{2} = 75 \text{ stroke}$$

$$\text{Total Time} = 75 \times 1.428 = 107.1 \text{ sec}$$


## Bonding materials

↓  
must be strength, toughness, hardness & temperature resistance  
to hold the abrasive grains together




Grinding = material removal by an abrasive bonded grinding wheel rotating with high speed.

Grinding wheel (basic parameters)




↓ means the substance that hold the abrasive grains.

the surface of the grinding wheel



two types



- Aluminum oxides
- Silicon carbides

- Diamond
- Cubic boron nitride

↑ 4x strength  
diamond

Aluminum oxides → grinding ferrous & high strength alloys  
(Knoop hardness ~ 2100)

silicon carbide → grinding aluminum, brass, and stainless steel  
cast iron & certain ceramics (~ 2500)

cubic boron nitride → grinding hardened steel & aerospace alloys (~ 5000)

Diamond → grinding ceramics, cemented carbides and glass (~ 7000)

Grain size → size of abrasive particles.



250

8

↓  
softer material

↓  
for harder material

& for lapping & superfinishing.



## Related Abrasive processes

Honing → uses bonded abrasive particles for making round hole

Lapping → for production of surface of extreme accuracy & smoothness

super finishing → similar to honing but shorter stroke  
 → lower pressure between tool & work piece  
 → lower work speed  
 → smaller grit size

Polishing → removes scratches & burrs using abrasive material attached to a polishing wheel rotating at high speed of around 38 m/min.  
 → Abrasive grains are glued to the out side periphery of flexible wheel.

Buffing → similar to polishing but used to form a high luster surface  
 → wheels are softer  
 → very fine grit size mixed in buffing compound.  
 → perform manually.

→ The bond holds the abrasive grains together & impact cutting performance.

→ Wheel grade is bond strength between abrasive grits, largely depending on the proportion of the bonded material in the wheel.

# Mechanical Energy Processes

Ultrasonic machining

Water Jet cutting

Abrasive water jet cutting

Abrasive jet machining

\* Conventional machining Vs. Non Conventional machining

1- **contact and tool wear**

- in traditional process (conventional machining), there is a contact between the tool & the workpiece, causing friction & tool wear.
- in non conventional process, there is no contact, tool wear is minimum or not a major concern.

2- **material removal rate**

- in conventional machining it's limited by the mechanical properties of the material, so struggles with hard-to-cut materials
- non-conventional machining handles difficult to cut materials such as ceramics, fiber reinforced composites

3- **work piece motion & shapes**

- relative motion between the tool & workpiece is rotary or reciprocating so it is → limited to circular or flat surfaces
- designed specifically to handle these complex shapes

4- **complex features**

- struggles with machining small cavities, slits, holes
- handles these features

5- **cost**

- Traditional processes → simple, inexpensive machines
- non-traditional → expensive machines & skilled labor

So, back to mechanical process, material removal is achieved using **mechanical energy** → applied in a form of

- **High frequency vibration**
- **Kinetic energy of abrasive jet**

We have

- ultrasonic machining (USM)
- Abrasive jet machining (AJM)
- Water jet machining (WJM)




# NON-TRADITIONAL PROCESS

A group of processes that don't use a sharp tool instead we use various techniques like mechanical, chemical, electrical & thermal to remove excess material.

Purpose: It's used when the conventional tools are not effective.

- 1- Mechanical energy process
- 2- electrochemical machining process
- 3- Thermal energy process
- 4- chemical machining


Why non traditional processes are IMP?



Requirements:

- high hardness & strength
- too flexible or slender (Delicate) → because it can't withstand the forces in conventional pr.
- complex shapes such as internal & external profiles
- surface finish or tolerance, better,
- Temp. rise or residual stresses are undesirable

Classification of Nontraditional processes → Type of energy used




## ADV:

- Low capital cost
- suitable for all types of materials
- less vibration
- good for difficult to reach areas
- no heat generation
- Cut intricate holes

## D.AV

- Low material removal rate (slower)
- particles are embedding in the workpiece affecting the quality
- Accuracy Affected by particles spread.
- ~~Am~~ Abrasive powder can't be reused

## Application



# ABRASIVE JET CUTTING

A high-pressure stream of fine-grained abrasives, mixed with air or suitable gas is directed onto the workpiece surface via nozzle.


The material is removed through the erosive action of the abrasive particles.

How it differs from sandblasting


The grains are finer, offering more control. This allows for precision cutting & is not just for surface cleaning like in sandblasting.

primarily used for cutting hard and brittle materials like glass & ceramics, also effective for thin materials & those sensitive to heat.

## parameters



## factors affecting the MRR



# Abrasive Water Jet Machining

## How it works

- A jet of water mixed with tiny abrasive particles to cut materials
- The cutting rate in traditional water jet is low, especially for ductile materials
- The presence of the ~~water jet~~ <sup>abrasives</sup> reduces cutting forces & enabling the machine to cut thick & hard materials

Why AWJM developed?

↓  
To cut materials that can't stand high temperatures for stress distortion or metallurgical reasons such as wood & composites and Traditionally difficult to cut materials

## Ultrasonic Machining (USM)

- Abrasive particles mixed with liquid (slurry) & this liquid is & flows between the tool & the work piece in a high velocity, while the tool vibrates at low amplitudes & high frequency.
- Tool oscillation is perpendicular to the work surface
- Tool is fed slowly into work

## Application

- hard, brittle materials
- ideal for creating non-round holes or holes with curved axes
- coining operations

What is ultrasonic waves? are sound waves with frequency higher than 20,000 Hz

- energy sources (mechanical, electromagnetic, thermal energy) can create them
- can travel through
  - gases
  - liquids
  - solids

complete →

# WATER JET MACHINING

involves directing in high pressure & velocity to the surface to be machined. The kinetic energy of the water jet converted into pressure energy upon striking work piece. , the kinetic energy reduced to 0 after impacted

## Material removal mechanism

If the local pressure that generated by the water jet exceeds the strength of the work piece, causes the material to erode & forming cavity on the surface.

↓ small area    ↑ high energy density.

\* Water is the most common fluid used, we can add alcohols, oil --- to improve the fluid characteristics

work piece material → soft metals  
→ paper  
→ plastic  
→ frozen food  
→ cloth  
→ wood

WJM is not effective for brittle → fracture  
Ductile material effective

## ADV

- no heat produced
- friendly manufacturing
- flexible cutting
- minimal burr production
- no crushing or burning
- ease of automation


## EQUIPMENT

pump with intensifier    cutting head    filter unit

↓  
including the nozzle for focusing the water jet & the system for worktable movement to guide the cutting process

\* used to cut narrow slots in flat surfaces

## Abrasive interaction



## Force distribution

As the tool moves down, it impacts abrasive particles with increasing force

→ At the lowest position, maximum force acts on the largest abrasives grits larger than the gap penetrate both the tool & workpiece, depending on their size & hardness of the surface.

## \* Magnetostrictive transducers

converts the magnetic energy into ultrasonic vibration

Certain materials, like metal & alloys, change their shape when exposed to a magnetic field → (magnetostrictive effect)

## \* Piezoelectric transducers → more efficient than ↑

converts electric energy into ultrasonic vibration

materials like quartz crystals or ceramics, generate mechanical vibration when electricity is applied to them → piezoelectric effect

→ natural or synthetic single crystals → quartz

→ ceramics (barium titanate) → have strong piezo-electric behaviour

they are better than over crystals

because they are easier to shape by casting, pressing & extruding.

## PRINCIPLE OF MACHINING

### 1- Material Removal Mechanism

material is removed by micro-chipping or erosion caused by abrasive particles, driven by a vibrating tool into the workpiece surface.

the tool is made from softer material than the workpiece is oscillated by the booster and sonotrode.

- the vibrating tool forces the abrasive particle in the slurry into a gap between the tool & the workpiece.

The tool starts from its upper position & moves down toward the workpiece.

the tool's speed is zero, but as it moves down, its speed increases maximum speed at the middle of the stroke

## Working principle

the tool is fed toward the workpiece (+) in precise & controlled rate  $(0.2 \frac{mm}{s})$   
the electrolyte flows between them to carry away

the dissolved metal & maintain the gap

ensures precision ← the gap remains steady 0.4mm → ensure not to contact

uniform metal removal cations → moves toward the cathod

anions → moves toward the anod

electrons moves from

the anode to the cathod

the electrolyte not only dissolves metal but also ensures the shape of the tool remains unaffected

(ensures only the workpiece dissolved, while the tool remain unchanged)

the electrolyte flows at high speed  $3-30 \text{ m/s}$  ?

← wash away the dissolved material

↓ Avoid clogging of the gap between the tool & the workpiece

→ ensures smooth continuous machining

## MRR

the closer the tool is to the work piece, the faster the metal dissolve.

This is why the gap width is inversely proportional to the rate of material removal.



# ELECTROCHEMICAL MACHINING (ECM)

Work piece  $\rightarrow$  anode (+)

Tool  $\rightarrow$  cathode (-)

material removal happens through anodic dissolution

the process use electric current to dissolve the material at the anode in a electrolyte

a rapidly flowing electrolyte separates the tool & the work piece

$\rightarrow$  conducts the current

$\rightarrow$  removes heat generated during the process

$\rightarrow$  flushes away dissolved material

ECM is similar to processes like

electro plating

metal coating are

deposited upon the

surface of cathodically polarized metal

(adding a metal coating to an object using electricity)

electro polishing

involve anodic dissolution but

slower MRR, compared with ECM

(making a metal surface smooth & shiny)

How material is removed?

Material removal happens because the workpiece is the anode & electrolyte dissolves the metal turn it into tiny particles & mixed with the liquid (electrolyte)

• At the anode (+), metal dissolves into electrolyte as iron ions ( $Fe^{2+}$ )


• At the cathode (-), hydrogen gas is released

- the flow of the electrons in the circuit drives the movement of the ions in the electrolyte




← HOW IT CAN BE DIFFERENT than metallic conductors of electricity?

## APPLICATION



## TWO MOST COMMON PRODUCT OF ECM



## ECONOMICS OF ECM

- economical for large production → +50 units
- Multi-tool setup
- faster for large cavities → faster than EDM

# ECM IMP. COMPONENT


## 1- POWER

- the power needed to operate the ECM, supply the electric potential difference needed
- the current density must be high
- the gap between the tool & workpiece must be low, for higher accuracy, the voltage must be low to avoid short circuit.

## 2. Electrolyte circulation system

- the electrolyte must flow in high speed → to insure a good removal of dissolved material & heat.
- pump, filter, reservoir, sludge removal system & treatment units
- electrolyte stores in a tank

## 3. CONTROL SYSTEM



The **CURRENT** DEPEND ON THESE PARAMETERS & the feed RATE

### ADV


- no cutting force
- no heat generation affected zone
- high surface finish & accuracy
- Relatively fast
- no tool wear
- machine hard materials

### D. ADV

- expensive (high cost)
- electrolyte issues
- space requirements
- Energy consumption
- Material limitation → only works with electrically conductive materials



\* Application of grinding hard materials



## Electrochemical Deburring (ECD)

is a specialized application of ECM design to remove burrs or round sharp corners in metal parts produced by conventional machining (Drilling)

## Electrochemical grinding (ECG)

special form of ECM

It's combination of electrochemical machining & conventional grinding.

the grinding wheel with conductive bond material acts → cathode & work alongside the electrolyte to remove material from the work piece (anode)

1- grinding wheel

made of metal bond combined with abrasive particles

2- non-conductive abrasive particles

acts → spacers between the grinding wheel & the work piece & maintain a constant gap.

3- electrolyte flow

↳ flows through the gap

### \* Material Removal Mechanism

Material is removed by combination of

↓  
electrochemical  
dissolution  
removes → 90%

↓  
Abrasive action  
the grinding wheel  
removes any  
residual material

### \* Limitation

↳ due to ~~small~~ electric field effects, inside corner & radii smaller than 0.25 mm hard to achieve

## \* EDM tooling

- electrode materials

- ↳ graphite
- ↳ metal alloys

- electrode wear



the electrode wear out during Machining requiring multiple tools for large & ~~small~~ complex cavities

### Advantages

- good for machining intricate shapes
- No physical contact
- versatility  
↓  
hard materials & fragile parts


### Dis Advantages

- slow process  
MRR is slower than the traditional Methods
- Tool wear
- surface finish  
↳ often required post-processing to enhance the surface finish

### Applications

- ↓  
Mold & Dies
- ↓  
small, delicate parts
- ↓  
Machining holes at acute angles
- ↓  
Exotic & hard to machine materials

# THERMAL ENERGY PROCESSES



\* Thermal energy processes are machining processes where high local temperature are used to remove material by fusion or melting  $\rightarrow$  turning into gas.

\* can be used only on electrically conducting work material.

\* surface finish is often poor, requiring additional process

## ELECTRIC DISCHARGE MACHINING (EDM)

know (sparks erosion machining)

removes material by eroding it through electrical discharges (sparks) between the tool & the work piece

$\rightarrow$  deal with material that are electrical conductors

set up  $\rightarrow$  the tool (electrode)  $\Rightarrow$  -ve terminal (cathode)

$\rightarrow$  the work piece  $\Rightarrow$  +ve terminal (anode)

Both are submerged in dielectric fluid  $\rightarrow$  Cools the material & removes debris

small gap is maintain between the tool & the work piece

when voltage is applied  $\rightarrow$  sparks are discharge across the fluid

$\downarrow$   
melt & vaporize material  $\leftarrow$  generating heat

- each spark erodes a tiny amount of metal

- the gap between the tool & the work piece is controlled by numerical control (NC) system to maintain precision

parameters

1. current  $\rightarrow$  generating current  $\rightarrow$  more powerful sparks

$\rightarrow$  this can creat larger craters & result

2. frequency

in a rougher surface finish


Increasing the freq.  $\rightarrow$  smaller craters & smooth surface finish but slows down the MRR.

MRR directly proportioned to the current


## Application

- Die & Mold Making
- Intricate Designs
- Internal cavities

## ADV



## Limitation






# WIRE EDM (WEDM)

special form of EDM

that use a small-diameter wire to electrode to cut a precise path (kerf) in a conductive workpiece.

- commonly used for production intricate shapes & small details

Components:



Process

The wire electrode travels along the programmed path (like a bandsaw), while cutting the material with sparks generated by electrical discharges.

Cutting Mechanism


↳ the wire does not touch the work piece instead use spark erosion to melt & vaporize the material

- can cut plates up to 12 inches thick
- precise cut for internal cavities (requires a pilot hole for threading the wire)
- can achieve high accuracy for intricate & delicate designs
- 0.005 inches → thin of the wire
- the wire is strong and tough but only used once (Disposable)
- the kerf (gap left by the wire) is small

## ADV

- non contact process.
- high precision
- Material versatility.

## Design for consideration



## Plasma arc cutting (PAC)


uses a plasma stream operating at very high temperatures to cut metal by melting.

# LASEM BEAM MACHINING (LBM)

A non contact thermal process that uses highly focused Laser beam to remove material by vaporization or ablation

• A laser generates a concentrated beam of light energy, which is directed onto the workpiece.

## Key component



## Workpiece MR. mechanism

Heat from the laser beam causes vaporization or melting of material.

• Can replace a conventional process like punching or shearing

## IMP. factors for workpiece material

