28. Consider the following statements:	
The tool life is increased by	
1. built up edge formation	
2. increasing cutting velocity	
<ol><li>increasing back rake angle up to certain value</li></ol>	
Which of these statements are correct?	

d. 1, 2 and 3 a. 1 and 3 b. 1 and 2 c. 2 and 3

## 29. Consider the following mechanisms:

1. Geneva gearing 2. Rack and pinion 3. Ratchet and pawl

Which of these mechanisms are used to index the work table on a transfer machine?

a. 1 and 2 b. 2 and 3 d. 1, 2 and 3 c. 1 and 3

30. Consider the following statements in respect of a grinding wheel of specifications, 51-A-36-L-7-R-23, using the standard alphanumeric codification:

1. Abrasive used in the wheel is aluminium oxide 2. The grain size of abrasive is medium

3. The wheel grade is medium hard

4. It has an open structure

5. It has resinoid as bonding agent

Which of these statements are correct?



## 31. Which of the following are produced by slush casting?

a. Hollow castings with thick walls b. Hollow castings with thin walls

c. Thin castings d. Thick castings

## 32. Which one of the following welding processes consists of smaller Heat Affected Zone (HAZ)?

- a. Arc welding b. Electron beam welding
- d. Thermit welding c. MIG welding

## 33. Gear shaping is a process of manufacturing gears. Which one of the following principles is employed by it?

a. Form cutting with gear b. Generating tooth form with a reciprocating cutter.





## 38. Which one of the following is not an electric resistance method of welding?

a. Electro slag welding b. Percussion welding

c. Seam Welding d. Flash welding

## 39. In one setting of rolls in a 3-high rolling mill, one gets

a. one reduction in thickness b. two reductions in thickness

c. three reductions in thickness d. two or three reductions in thickness depending upon the setting

40. At room temperature, which one of the following is the correct sequence of increasing hardness of the tool materials?


a. Cast alloy-HSS-Ceramic-Carbide


c. HSS-Cast alloy-Carbide-Ceramic

b. HSS-Cast alloy-Ceramic-Carbide

d. Cast alloy-HSS-Carbide-Ceramic








# 4:03 PM

40% 🔳 🕂

## dropbox.com




47. The nozzie part of the water jet machining is made of a) tungestun carbid or sapphire b) aluminum c) steel d) coppe 48. which of the following is not true for the abrasive jet machining a) Low capital cost b) low vibration c) high metal removal rate d) no heat is 49. which of the following material cannot be cut with water jet cutting c) composites d) plastics b) glass a) metals 

改国

a) EDM

THE OF STREET, AND STREET, STR

Tout



a) 89.9 b) 99.8 c) 109.9 d) 59.9

36. Semicontinuous chips with large zones of low shear strain and small zones of high shear strain are called


a) continuous chips b) serrated chips c) curl chips d) discontinuous chips

37 the following figure refers to ...... manufacturing process



d) none of them c)reaming b) sawing a) broaching

39. the following figure refers to ...... manufacturing process



a) blade sawing b) Milling c) reaming d) hacksawing 40. the following figure refers to \_\_\_\_\_\_ manufacturing process



a) Planning b) turning c) milling


41. the following figure refers to ...... manufacturing process



c) planning d) tapping b) turning a) shaping 42. Tools made up of carbides are extremely hard having Rockwell hardness varying from d) 590-993 HRC c) 10-23 HRC b) 90-93 HRC a) 0-13 HRC 43. The most common drill material is d) carbide c) Diamond b)Ceramic tipped a) High speed steel 44. Which of the following materials has the highest machienability index. d) Aluminum c) Magnesium b) Copper a) Steels 45. A cutting fluid should have c) high thermal capacity d) all of them b) low toxicity a) High conductivity

46. in abrasive jet machining the grit size is of an order of

c)15 centimeter d) 15 meter b)15 milimeter a)15 micrometer 47. The nozzle part of the water jet machining is made of d) copper c) steel b) aluminum a) tungestun carbid or sapphire 48. which of the following is not true for the abrasive jet machining b) low vibration c) high metal removal rate d) no heat is generated in work piece. a) Low capital cost 49. which of the following material cannot be cut with water jet cutting d) plastics c) composites b) glass. a) metals 50. the following figure refers to ...... manufacturing process



b) PLASMA arc

c) ultrasonic

d) abrasive jet

d) shaping

### in old abolite machining, the tool moves

- a. moves in transverse direction
- b. moves in longitudinal direction
- c. vibrates in transverse direction
- d. vibrates in longitudinal direction

(Ans:d)

## In which of the following processes, the shape of tool is not same as that of cavity produced?

- a. Ultrasonic Machining
- b. Electrical discharge Machining
- c. Electrochemical Machining
- d. Plasma arc machining

(Ans:d)

## In which of the following processes, a nozzle is used?

- i. Plasma arc machining
- ii. Ultrasonic Machining
- iii. iii. Abrasive jet machining
  - a. i&ii
  - b. ii&iii
  - c. i&iii
  - d. i, ii & iii

(Ans:c)

In which of the following gases is not used in Abrasive jet machining?

- a. Air
- b. Nitrogen
- c. Carbon di-oxide
- d. Argon


(Ans:d)

 In an orthogonal cutting, the depth of cut is halved and feed rate is double. If the chip thickness ratio is unaffected with the changed cutting conditions, the actual chip thickness will be

- a. Doubled b. Halved
- c. Unchanged d. None of the above

## 2. Cast iron during machining process produces

- a. Continuous chips
- b. Discontinuous chips
- c. Continuous chips with built up edge d. None of the above





## 8. The powder metallurgy technique for the product of precision component is characterized mainly by reduction in

a. Material cost b. Machining cost

c. Equipment cost d. None of the above

### 9. Magnetic arc blow is

a. A recent welding technique b. Used to weld hard materials

c. Phenomenon on occurrence of splatter because magnetic field is created in d.c. arc welding.

d. None of the above

## 10. In rolling operation the roll rotate with surface velocity

a. Exceeding the speed of incoming metal b. Lower than the speed of incoming metal

c. Equal to speed of the incoming metal

d. None of the above

## 11. Process of extrusion is like

a. A viscous lubricant pouring the mouth of container

b. A tooth paste coming out of its tube

c. Hard particles thrown out of a nozzle under air pressure

d. None of the above

## 12. Material good for extrusion is

- a. Stainless steel
- c. Low carbon annealed steel

d. None of the above


b. Brass

## 13. The method most widely used for production of metal powder for use in powder metallurgy is

- a. Liquid metal spray b. crushing using impact
- c. Electrolytic deposition d. None of the above

## 14. In braze welding the filler material is


- a. Distributed by capillary action
- b. Melted and deposited at the point w 3de 11 of 18
- d. None of the c. Both a and b





b) PLASMA are

a) EDM



50 the following figure refers to 49 which of the following material cannot be cut with water jet cutting a) metals a) Low capital cost b) low vibration c) high metal removal rate t th) glass c) composites manufacturing process d) plastics

a) tungestun carbid or sapphire 48. which of the following is not true for the abrasive jet machining 47. The nozzle part of the water jet machining is made of a)15 micrometer 46, in abrasive jet machining the grit size is of an order of 45. A cutting fluid should have a) High conductivity b)15 millmeter b) aluminum b) low toxicity c)15 cantimates c) high thermal capacity c) steel

a) Steels b) Copper c) Magnesium

a) High speed steel b)Ceramic toped 44. Which of the following materials has the highest machienability index 43 The most common drill material is

42 Tools made up of carbides are extremely hard having Rockwell hardness varying from 4) 0-13 HRC a) shaping 6190-93 MRC b) turning e planning c) 10-23 190



41 the following figure refers to CALCEL OF manufacturing process a) Planning

al tilade sawing b) Milling

ĮĮ,

2. - 4 52

39. the fol Stating Spirst rotans to

Mr. the

C LINGARY 20

manufacturing process

a) and staning

b) nove milling

the following figure refers to

Rout thom

b) som ated chips

manufacturing process

c) curd chips

B 166 [4

6 501(7

616519


11

munutacturing process

40. the following figure refers to

manufacturing process

Buncheoug (e







### 14. In braze welding the filler material is

a. Distributed by capillary action

b. Melted and deposited at the point where the weld is to be made

c. Both a and b d. None of the above

### 15. Amount of current necessary in resistance welding is of the order of

- a. 1-2 kVA/cm<sup>2</sup> b. 2.5-4 kVA/cm<sup>2</sup>
- c. 4.5-6.2 kVA/cm<sup>2</sup> d. None of the above

16. In the relation for cutting tool life VT<sup>n</sup>=C, the numerical value of n for high speed steel tools vary in the range of

a. 0.1 to 0.15 b. 0.20 to 0.25

c. 0.25 to .40 d. None of the above

17. In a turning operation the tool life of the carbide tool was found to be 20 minute and 100 minute at cutting speeds of 120 m/min respectively. What will be the tool life of the tool under the same condition but at a cutting speed of 100 m/min?

a. 31 minutes b. 41 minutes c. 36 minutes d. None of the above



### 18. Product layout is known as

- a. Analytical layout b. Synthetic layout
- c. Static production layout d. None of the above

## 19. In which of the layout, similar operations are performed at the same place always

- a. Process layout b. Product layout
- c. Combination layout d. Fixed position layout

## 20. Which of the following types of flames has a supply of excess of acetylene as compared

## to oxygen?

- a. Oxidizing flame b. Neutral flame
- c. Carburizing flame d. None of the above

### 21. Directional solidification can be achieved by providing

- a. chills and chaplets b. chaplets and padding
- c. chills and padding d. chills, chaplets and padding





a) counter sink tool b) reamer tool c) gun drill tool d) counter bore tool
16. drill tool material used for high production and CNC machines
a) HSS b) Carbide tipped drills c) low carbon steel d) all of them
<ul> <li>17. A peripheral milling operation is performed on the top surface of arectangular workpart which is 400 mm long by 60 mm wide milling cutter, which is 80 mm in diameter and has five teeth, overhangs the width of the part on both sides. Cutting speed = 70 m/ chip load = 0.25 mm/tooth, and depth of cut = 5.0 mm. the feed rate is         <ul> <li>a) 483 mm/min</li> <li>b)843 mm/min</li> <li>c) 348 mm/min</li> <li>d) 438 mm/min</li> </ul> </li> <li>Built up edge can be reduced by</li> </ul>
a) increase depth of cut b) decrease the rake angle c) Both a and b d) use effective cutting fluid
19. As the lead angle increases the undeformed chip thickness
a) increases b) don't affected c) decreases d) none of them
20. In, the axis of cutter rotation is parallel to the workpiece surface.
a) slab milling b) ball milling c) end milling d)face milling
21. In milling process, Max chip thickness is at the end of the cut
a) ball milling b) down milling c) end milling d) up milling
22. one of the following is not true for the upmilling process
a) cutting process is smooth b) tooth engagement is a function of workpiece surface characteristics, and contamination or the surface affect tool life c)tendency for the tool to chatter d)none of them
23. Because of the resulting high impact forces when the teeth engage the workpiece, this operation must have a rigid setup, and backlash must be eliminated in the table feed mechanism in milling process
a)up milling b) end milling c) down milling d) ball milling
24milling process can produce a variety of surfaces at any depth, such as curved, stepped, and pocketed.
a) end milling b) down milling c) up milling d) referral milling
25. in milling process the problem of burr formation may be related to
a) incorrect entry and exit angles b) dull cutting edges c) feed and depth of cut too high d) all of them
26. the component that supports the table and can move in the transverse direction is usually called
a) saddle b) overarm c) compound wrest d) knee
27. one of the following is not true for the material removal processes compared to forming
a) waste of material b) time consuming process (c) bad dimensional accuracy d) straight edges and surfaces
28. Which of these statements are correct? built up edge may be reduced by:
1. decreasing depth of the cut 2. Increasing cutting velocity 3. increasing back rake angle
a) 1, 2 and 3 b) 1 and 2 c) 1 and 3 d) 2 and 3
*A turning operation is made with a rake angle of 10°, a feed of 0.010 in/rev and a depth of cut = 0.100 in. The shear strength of

material is known to be 50,000 lb/in<sup>2</sup>, and the chip thickness ratio is measured after the cut to be 0.40. Answer questions 29, 30

d) 0.8216

d)9.22°

32.

29. The shear angle is

c) 92.2° b) 22.9° a) 29.2°

30. The sheer force is

c)821 lb d) 128 lb a) 812 lbb) 182 lb

31. the cutting force is

d) 236 lb c) 623 lb b)326 lb a) 632 lb

32. the thrust force is

d) 22 lb c) 229lb

b)129 lb a)922 lb \*Tool life tests in turning yield the following data: (1) when cutting speed is 100 m/min, tool life is 10 min; (2) when cutting speed is 75 m/min, tool life is 30 min. Answer questions 33, 34, and 35 using Taylor equation

33. the value of the exponent n is

c) 0.6218 b) 0.2618 a) 0.1268

34. the value of the constant C is

d)578.12 c)157.82 b) 182.75 a) 287.15